JAN 21 1999

SECTION

STATE OF MICHIGAN COUNTY OF CASS

	7.000141	•	₩.	
ΑI	Downers.	4.	4	
276	Recor	4	=u	

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	Dacarda
Filing Requirement of Act 74, Mich. P.A. 1970	Heren de
Casa Caunty Damanumantation	12-22-1

For corners in	Cass Coun	ty Remonumentation	12-22-1998 15:49	1:42
Cass (County)	Located In:	Corner Code #	Ann L. Simmons	85 7
		_	REGISTER OF DEED	e e e
 Public Land Survey W 1/4 cor. Sec. 6 	T <u>5S</u> R <u>16W</u>	A-2	Liber 00003	nog for
	TR		Liber WUWUJ	g \$
2. Property Controlling S	TR TR			Ratified by
in Section S 3. Miscellaneous S	TR TR			Ratii In A
Property in Sec. S	TR		Register of Deeds	Stamp & File Number
4. Lot No, Recorded	Plat			
5. Private Claims			- A B C D F F	G H 1 J K L
			2 - 6 6 4	3-1-2-1-1-
	, in a field survey onO			10
hereby state that under requirements of in lines 1 and 2 above were in confort	mance with regulations and rule	s therefore as required in the	e -	12
current manual of survey instructions o Management or by a decree of a Court	f the United States Department	of the Interior, Bureau of Land	a s	15 4 13
and 5 above were in conformance wit	th the rules of the Michigan Boa	rd of Land Surveyors or by	a	
Decree of a Court of Law; established, below:	, re-established, monumented, re	ecovered, found as expressed	d 8 19 20 21	22 23 24
•	the grown to	. No week a second	9	
NOTE: Not more than 2 corners, all in on this certificate.	the same town and range, may	pe recorded	10 30 20 28	
			11	
A. Description of original monume	nt and accessories and/or sul	osequent restoration:	$12 \longrightarrow 31 \longrightarrow 32 \longrightarrow 33$	36
This corner was not originally set. I	Found no history of this come	er of being set.	134	
		•		
B. Description of corner evidence	found and/or method applied	in restoring or reestablish	ning corner:	
Found nothing at this position. Set	3/4" pipe at the prorated dist	ances and on line betwee	n the East 1/4 corner Sect	tion 1, T5S, R17W an
the Southeast corner of Section 1, 1	T5S, R17W.			,,,,,
		•		
				1
			.	
			:	
C. Description of monument for	corner and accessories estab	olished to perpetuate locat	ting the position of the cor	ner:
Set 3/4" iron pipe 24" long with surveyors. This monument is ac	cepted as the best availab	IT box. This position was	vas not established by o	riginal government
East 1/4 corner Section 1-	5-17 3/4" iron with brass	cap North 50.16'	ROIL OF LIFE COTTIET.	
PK Nail in 16" Walnut	North 18 degrees Eas	st 31.45'	OF MICH	
PK Nail in 11" Walnut	East	12.47	R C.	
PK Nail East side Power Po CL N-S Gravel Road	ole South 35 degrees Wo West	est 65.41' 💆 🔗 12.00'	DALEL. KESLER	
5 6.6.6.11000	******	12.00 温	LAND SURVEYOR *	
			No. 38117 .e.	
•			No. 38117 ASED LAND SURVEY	
		****	LAND SUR THE	
~ n 1	V.	est 65.41'	tantorise.	
Signed by				Dec. 22, 1998
Surveyor's Michigan License No.	38117			,