MAY 1 5 1997

COMMISSION

CASS COUNTY REMONIMENTATION

Liber 00003 Page 0071

LAND CORNER RECORDATION CERTIFICATE COUNTY OF CASS

STATE OF MICHIGAN

Filing Requirement of Act 74, Mich PA 19705

| Fο | r corners in Ontwa 1 | Township Township | Sincist of Act 14, Mich. P | A. ISTURE | corae |] | | | | | | Ł | |
|---|---|---|---|-------------------------------------|--------------------|---|----------------------|-----------------|------------------|--|--------------|-------|--|
| | Cass (County) | Located In: | Corner Code ## | 01- | -31-19 | 997 10 |):51: | 56 | | Ü. | | j | |
| 1. | Public Land Survey | T <u>8S</u> R <u>15W</u> T R T R | A-8 | Ann L. Simmons REGISTER OF DEEDS | | | | | | Railfied by Peer Group In Accordance With P.A. Preimen Dogle | | | |
| | Property Controlling in Section | T R S T R S T R | | | | | | | | Patrilod . | In Accordan | 100 C | |
| 3. | Miscellaneous Property in Sec. | S T R S T R | | Regist | ter of E | eeds (| Stamp |) & F | | | | al | |
| ١. | Lot No | , Recorded Plat | | | A D | 0 0 | | | | | | | |
| | | | | | Â | C D | E F | Ť | | J 1 | I | Γ | |
| | | | | 2 | ² 6- | | 4 - | + | å— | - <u>-</u> - | 1 | | |
| | | | | i ³ | 3 | | + | + | \vdash | - | + | - | |
| | Christian F. Marback | h, in a field survey on <u>Septemb</u> | er 6 40 96 | | ¹ | — <u>в</u> — | - | ┼-1 | ₽ | 1/1 | | 2- | |
| to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land | | | | | 5 — 18— 7 — 18— | 17_ | 16- | 1-1 | 5 | —14— —14— | -1 | 3- | |
| Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a | | | | | 19- | 20 | 21- | _2 | <u>!</u> 2 | 23 | <u>2</u> | 4- | |
| | | , re-established, monumented, re-m | | | ' —— | ╂┷┼┷ | + | + | ┼┼ | + | Н | _ | |
| хp | ressed below: | | | 10 |) 3 0 | -2 9 | 2 8- | | 7 | 26 | | 5- | |
| Ю | TE: Not more than 4 on this certificat | corners, all in the same town and | d range, may be recorded | 1¦1 12 | II | | ++ | +- | <u> </u> | + | \prod | _ | |
| | | - | • | 13 | 1 9 | 32 | 33- | 7 | î | 35- | 3 | 6- | |
| | | al monument and accessories and nt: Set post corner to l Post (Brookfield, 18 | Frl. T8S, R15W and I | | .68 c | hains | Eas | t o | £ 3 | 7th | Mi | 16 | |
| | Accessories: | 10" Burr Oak, N 84° E (No other bearing tree | | | : | | | | | | | | |
| : | Subsequent Resto | oration: (1) Set ½" reba Nail in 20 | ar over stone, (Pres O" Maple, N 26° E - | | | | asp | hal | t r | oad | • | | |

East - \pm -8.0'; 1" iron under North & South fence, West - 16.0';

(Continued on reverse side)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Evidence Found: (A-8) A railroad spike was found +/- 8.0' West of centerline road, Old monument box found also; A 1" iron was found West 16.0' (No fence); A

steel post was found East 35.5' (No fence); An iron with cap (#18662)

was found West 33.0' (No fence)

(A-7)CHRISTIAN MARBACH LAND SURVEYOR No. 37280 SED LAND

A rebar was found (See N.C. Jones - Liber 1, Pg. 317) Distance (A-8) to (A-7) measured as 2552.17; Notes obtained from Prestine indicate distance (A-8) to (A-7) as follows:

2552.50' (Prestine) 2552.60' (Dreher)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced Railroad Spike with 1" iron pipe (30" long) with aluminum tablet set in 8" diameter monument box. Monument box is flush with the asphalt surface of Conrad Road. Tablet is stamped "Cass County Remonumentation" and is accepted as careful and faithful perpetuation of the original corner.

Accessories:

Masonry nail set in 8" Locust, N 90° E - 34.20" Masonry nail set in 4" Locust, S 87° W - 15.33'

37280

Street sign, N 10° W - 14.40' Iron with cap, N 90° W - 33.02'

(Continued on reverse side)

Date 12-9-96

A. (Continued)

1" iron under North & South fence, East - 32.0'

- (2) Found iron over stone, (Peirce 8/16/71) (Liber 1, Pg. 103)
 Nail in 30" Maple, N 26° E 66.5'; Center pavement, East +/-8.0'; 1" iron under North & South fence, West 16.0'
- (3) Set standard monument in monument box (Peirce 11/28/78) (Liber 2, Pg. 170)
 24" Maple, N 28° E 68.56'; 10" Oak, N 23°W 42.89'

C. (Continued)

1.00

Iron, N 90° W - 16.03'
Steel post, N 90° E - 35.5'
Centerline Conrad Road, E - +/- 8.0'

Liber 00003 Page 0072