REMONUMENTATION

APR 2 6 1995

Property Controlling

in Section

Miscellaneous

Property in Sec.

es schilly ed for record

AND CORNER RECORDATION CERTIFICATE			
Filing Requirement of Act 74, Mich. P.A. 1970	m. r. r		~ ~
CACC COUNTY DEMONINGUEATION 1534 UT - CY	YE.	₽#	20

COMMISSION	Filing Requirement of Act 74, Mich. P.A.
For corners in	CASS COUNTY REMONUMENTATION
0100	5.100 50011. 1,2.101.2.111.

Located In: Corner Code ## T 8S R 16W 1. Public Land Survey E 1/4 Cor. Sec. 4 T _____ R ___ T _____ R __

. T____R_ __ T ____ R _ ___ T ___ R __ ___ T ____ R ___ and Lim CLERK/REGISTER

STARS OF MODERAN

2 PAGE 394

Ratified by Peer Grot

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat	
5.	Private Claims	

Dale L. Kesler in a field survey on _ December 15, 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

- A. Description of original monument and accessories and/or subsequent restoration:
 - July 1828 William Brookfield Set post 40 Chains south of the Northeast corner of
 - Section 4 and 40 Chains North of Southeast corner of Section 4. 26" White Oak South 52 1/2° East, 88 Links, 10" Hickory North 55° West 91 Links
 Oct. 1874 J.C. Bradt Identified and re-witnessed 40 Chains north of the Southeast corner of Sec. 4 10" Yellow Oak North 52° East 56 Links,
 - 4" White Oak tree North 52 1/2° West 88 Links
 1974 & 1988 Robert Prestine Witnesses Found Railroad spike 48" Oak North 35° West 49.5', 30" Hickory tree South 70° West 36.4', 1/2" Pipe - West 33.0'
- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Railroad spike in monument box at the East Quarter corner of Section 4, T 8 S, R 16 W. In December 1994 measured 2649.93' to the Southeast corner of Section 4. In July 1991, Robert Prestine measured 2649.82' to the Southeast corner. County Surveyor notes show distance to be 40.16 Chains (2650.56'). Distance to adjacent corner was reasonable and consistent. Accepted R.R. Spike as best evidence of corner.

- 3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Set 3/4" standard iron pipe with aluminum cap in place of railroad spike and is accepted as a careful and faithful perpetuation of the original corner.

Set nail with washer on East side of 48" Oak, North 35° West - 49.50' Set nail with washer on North side of 30" Hickory, South 70° West - 36.40 OF Microset 1/2" Iron pipe - West 33.0'
Set nail with washer East side of 12" Poplar, South 20° West - 55.70'

DAILL

MID CURTERIOR

aned by 38117

___ Date ___

<u>December</u> 29, 1994