## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

E	corner	
rm	COUNCI	<b>\ III</b>

Chippewa (County)	Located In:	Corner Code #											
1. Public Land Survey	T R T R T R T R T R T R T R T R T R T R												
2. Property Controlling in Section	S 26 T 42N R 2E S 26 T 42N R 2E S T R	12 9											
3. Miscellaneous Property in Sec.	S T R S T R			Reg	ister o	Dee	ds Sta	amp a	& File	Numt	oer		
4. Lot No. , Red 5. Private Claims	corded Plat	40,000	1 A	В	C I	E	F	G	н т		ĸ	_ <u>L</u>	
	07/	16/2008	3			$\vdash \vdash$		- -	+	+	$\dashv$	+	$\dashv$
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2			4 1-	<del>†</del> ·	+-	<b> </b>	 	+	10-	1/1-	十	—1 <sup>1</sup> 2	ㅓ
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6				1 <del>8</del>		7	-16-		15		1	—  —13	
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 re-established, monumented, recovered, found as expressed below:				19		0	_21		-22-	_23 	1	_24. 	
NOTE: N. A. C. C. A. C.			10- 11-	30	+	9	<u>2</u> 8_		-2 <sup>1</sup> 7	<b>—26</b>	1	-2 <sup>1</sup> 5	
on this certificate.				-31		2	3′3- 		34	3'5_ 	1	—36 —	

- A. Description of original monument and accessories and/or subsequent restoration:
- (12-Sec. 26) South 1/16 corner Section 26. Not established in the original survey.
- (9-Sec. 26) East 1/16 corner, Section 26. Not established in the original survey.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (12-Sec. 26) Established the corner midway and on a straight line between the intersection of 1/4 lines of Section 26 1320.25' north and Quarter corner 1320.25' south.
- (9-Sec. 26) Established the corner midway and on a straight line between intersection of 1/4 lines of Section 26 1328.07' west and Quarter corner 1328.07' east.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.

Set measuring nail with MDNR tag in the side of:

Set measuring rail with MDNR tag in the side of:

Set measuring rail with MDNR tag in the side of:

12" W.Pine S32W

4" W.Birch S41E

9" Balsam N89W 16.72' do 9" Balsam N61E

11" Spruce N45W 15.38' do 8" twin Spruce

Bearings are magnetic.

(9) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" W.Pine S32W 21.38' mrkd "E1/16 BT" 4" W.Birch S41E 11.63' do 9" Balsam N61E 8.21' do 8" twin Spruce S86W 4.23' do Bearings are magnetic.

Signed by Surveyor's Michigan License No. 33986

Date

09/16/2008

For the Michigan Department of Natural Resources, Office of Land and Facilities

47112 47113 FORM APPROVED BY MICHIGAN STATE BOARD OF THE

AND Sepised Lay 14, 1975

Rervised Oct., 1995

STEPHAN J

SZYSZKOSKI LAND

SURVEYOR

· ·