MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.42. NR.6.E.

			Chippewa COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between sections 17 & 18
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Brass cap
WIT TNESSES	то	CORNER	4" Cedar - S 50 E - 11 Links
			12* Cedar - N 21 E - 39 Links
			5" Ceder S 53 N - 44 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division Survey crew, while making a survey in this area. This North and South line was cut through from the section corner 1/2 mile South, to the lake shore. The lakeshore was meandered in both directions to prove our position. A hard fire has burned this area, but one probable B.T., a Temarack, is still in place, badly burned.

Corner was placed and witnessed October 4, 1950.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 12/27/50