MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_43_ NR_6.E___

				Chippewa	COUNT
DESCRIPTION	OF	CORNER	Section Corner common to Sections 23, 24, 25, 26		
DESCRIPTION	OF	CORNER	MONUMENT	lm pipe with 4m brass	cap
WIT TNESSES	TO	CORNER	8m Cedar _	N_48° E	12½ links
				S_44°_E	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set Section Corner from one (probable) Tamarack stp; very poor condition.

There is evidence of old line blazes S-N-W from this point. Very old.

Corner placed and witnessed May 3, 1956.

SURVEYORS SEAL

SIGNED SILLY & Buckles DATE 5/11/56