

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 6.E ..

----- Chippewa ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 22, 23, 26, 27.

DESCRIPTION OF CORNER MONUMENT No corner set.

WITNESSES TO CORNER 11" Cedar N 78° E 31 links

6" Cedar N 37° W 26 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

An Iron Pipe and Concrete Monument has been set by unknown surveyor many
years ago.

Corner lies 30 links East and 177 links North of Bonners' temp. Section
Corner.

Corner found by Forestry Division Survey Crew while making a partial
re-survey of this area.

Re-witnessed Section Corner May 3, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buehler DATE 5/11/56
REGISTERED LAND SURVEYOR