MAR 0 9 1994

## LAND CORNER RECORDATION CERTIFICATE

93 DEC 29 PH 2: 47

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in CONSIN Chippewa	Located In:	C	orner Code =##	}	J. Roja Malsk			
(County)		Ū				ILE OL DE		
1. Public Land Survey	T44N R 11 T 43N R 11 T R T R		-13) Same -1 /Corner			יין טו עַּרֶ	C03	
Property Controlling     in Section	S T R S T R							
3. Miscellaneous	S T R			Regis	ter of Do	eds Stamp	e Eila N	umbar
Property in Sec.	S T R			rregia	- Del	ans Granih	or File Mi	er
4. Lot No , R	ecorded Plat	•						
5. Private Claims					A B C	DEF	GHI	JKLI
<del>-</del>					2 6-	- 5 4	1 3 l ·-	5
					3			
					4	- 89-	-10	-11-12
William L. Karr .					5		1 6	+
do hereby certify that under req in lines 1 and 2 above were in					6 18	-1716	161	_14
current manual of survey instru					7	111	1'	
Management or by a decree of a	Court of Law and/or that the	corner points	mentioned in lines 3	, 4 and 5	8 3	1 44 J.	22	23 24
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as					9 /	111		
expressed below:	e-established, monumented	, re-monume	ntea, recoverea, to		10 30	-2928	27-	26
NOTE: Not more than 4 co	veners all in the same too	un and rang	a may ba racarde		11	1		
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					12 31			
					13	-32	1 34	-3536
A. Description of original r	nonument and accessorie	s and/or sul	bsequent restorati			•	- <del>1</del>	-111
(D-13) ½ Corner	Common to Sections	<u> 32 &amp; 5</u>	(T44N-R1E)			11	griffina.	
							70 M	
	ablished by Austir ction Post	Burt fo	r William A.	Burt.				
Tan	marack 7	110°W	10 links			w	31/m	1
Tan	arack 10 N	151°E	29 links			12/	29/93	
	·							
						•		,-

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D-13) This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found no evidence of original corner. Found a North-South fence line on the North side of the road. Did not hold fence line. Re-established corner position midway and on line between the Southeast and Southwest corners of Section 32. position falls 20' West of extension of fence line to the North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (D-13) Corner is a 3/4" x 24" iron with plastic "Chippewa County Remonumentation" Falls 3' North of the centerline of Gogomain Road (East-West, paved). 20' West of extension of fence line to the North.

## Witnesses:

4" Spruce	N79°E	165.65'
Power Pole	S83°E	424.82
Power Pole	S01°E	48.50'
3" Spruce	N73°W	110.65

Signed by 27450 Surveyor's Michigan License No.

veyor's Michigan License No. 27430

NOTE: Bearings are compass bearings corrected for declination.

REVISED MAY 14, 1975 Distances are to a nail in side of witness objects unless noted. REVISED JAN., 1983

ILLIAM I KARR LAND URVEYOR