Property in Sec.

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD CHIPPEWA COUNTY STATE OF MICHIGALI



LAND CORNER RECORDATION CERTIFICATE

93 DEC 29 PM 2: 48

James Carlotte Comment	Filing Regu	irement of Act 74, Mich.
r corners in	r ming mequ	internetit of Act 14, mich.
Chippewa	Leasted In-	Comer Code att

PA 1970 Located In: Corner Code =## T 44N R 1E H-13) Same 1. Public Land Survey

/Corner T_43N_R_1E_ T R ___ R _ 2. Property Controlling in Section Miscellaneous

Register of Deeds Stamp & File Number

___ , Recorded Plat _ 5 Private Claims

William L. Karr , in a field survey on <u>December 1</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: (H-13) 1/4 Corner Common to Sections 34 & 3, (T44N-R1E)

1993: G.A. Meyers, L.S. 28418. Corner recorded in Liber 8, Page 8 of the Chippewalling between the Northeast Corner to the Nor County Corner Records. Set 1 iron midway and on line between the Northeast and Northwest corners of Section 3.

8" Fence Post N89°E 48.08' N35°E Power Pole 80.99' 12" Tamarack S17°W 65.02' 10" Tamarack N49°W 76.39

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H-13) This corner is being perpetuated as part of the Chippewa Remonumentation Program.

Found a 3" iron L.S. 28418 on centerline Gogomain Road. Found the four record witness objects. Record bearings to the objects are in error. Accepted corner position as found. Offset corner position prior to road reconstruction work. Replaced corner after construction completed. Added an additional witness.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a 3/4" x 24" iron with plastic "Chippewa County Remonumentation" <u>(H-13)</u> Corner falls on centerline Gogomain Road (East-West, paved). An old fallen fence line runs to the South.

Witnesses:

Signed by __

8" Tamarack N40°E 76.50' (existing nail) 80.99′ S54°E Power Pole (existing nail) Sawed Off Power Pole 48.05' (existing nail in top) South 4" Tamarack S18°W 47.62'

12" Tamarack N10°W 65.09' (existing nail)

27450 Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination.

Reviseo May 1

Distances are to a nail in side of witness objects unless noted.

WILLIAM L KARR

LAND

SURVEYOR

No.