MAR 09 1994

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD CHIPPEWA COUNTY STATE OF MICHIGAN

LAND CORNER RECORDATION CERTIFICATE

93 DEC 29 PM 2: 49

10

11

12

For corners in Chippewa (County)		Filing Requirement of Act 74, Mich. P.A. 197		A. 1970
		Located In:	Corner Code ##	S. Maller
1. Public	Land Survey	T R	F-13	REGISTER OF DEEDS
2. Proper in Sec		S T R S T R		
3. Miscel Proper	laneous _	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No	, Rec	corded Plat		A B C D E F G H I J K I
5. Private	Claims			2 6 5 4 3 2
		n a field survey on <u>Decem</u>		5
do hereby co	ertify that under requir	rements of P.A. 74 Michigan P.A	of 1970, the corner points montin	

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines $3,4\,\mathrm{and}\,5$ above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration: (F-13) South 1/4 Corner of Section 33 (T44N-R2E)

1840: Corner established by Austin Burt for William A. Burt. Set 4 Section Post.

11" Sugar N82°E 12 links 20" White Birch N74₺°W 53 links

·1983: Harry W. Goodwin, L.S. 5434. Corner shown on a survey recorded in Liber 441, Page 182 of the Chippewa County Records. Survey shows corner 26.70' East of the North 1/2 corner of Section 4. Survey calls for a 1/2" rebar with cap #5434.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

is being perpetuated as part of corner the Chippewa Remonumentation Program.

Found a $\frac{1}{2}$ " iron and remains of L.S. cap. Found corner falls 26.66 North $\frac{1}{2}$ corner of Section 4 (a $\frac{1}{2}$ " iron with remains of L.S. cap). Found corner falls 26.66' East of the Computed GLO distance is 26.73'. Accepted corner position as found and offset prior to road Replaced after construction completed.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (F-13) Corner is a 3/4" x 24" iron with plastic "Chippewa County Remonumentation" Corner falls 1' North of the centerline Gogomain Road (East-West, paved).

Witnesses:

16" Maple N46°E 58.89' 14" Cedar S42°E 81.617 6" Maple S15°W 88.07' 8" Maple N24°W 58.72' North & Corner of Section 4 West 26.66

Signed by _ 27450

Surveyor's Michigan License No. 27450
NOTE: Bearings are compass bearings corrected for declination. Revised MAY 14, 1975 Distances are to a nail in side of witness objects unless noted. REVISED JAN., 1983

VILLIAM L

KARR

LAND

SURVEYOR

No.

27450