467	Survey &	
BFI	MONUMENTATION	

CHIPPEWA COUNTY REMONUMENTATION CORNER

APR 2 6 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

_ COMMISS	LAND C	ORNER RECORDATION CERT		
For corners in Chippewa	SIGN Filing R	equirement of Act 74, Mich. I	P.A. 1970	
(County)	Located In:	Corner Code ≠#		
Public Land Survey	T 44N R 21 T 45N R 21 T R	W C-13 Corner	\$ 7.00 LAND CORN \$ 2.00 MSSR	
Property Controlling in Section	T R S T R S T R			P.H. RECEIPT# 2266 FOR RECORD - STATE OF MICHIGAN
3. Miscellaneous Property in Sec.	S T R S T R			Starnp & File Number
4. Lot No ,	Recorded Plat			
				E F G H I J K L
			3 5-5-	3 - 2 - 1 - 1
Keith R. Water	S	December 7 94	4 - } -	9-10-11-12-
in lines 1 and 2 above were current manual of survey inst Management or by a decree of above were in conformance w Court of Law; established, expressed below:	in conformance with regulations of the United States fa Court of Law and/or that the with the rules of the Michigan Ere-established, monumented corners, all in the same to	an P.A. of 1970, the corner points menions and rules therefore as required Department of the Interior, Bureau of ecorner points mentioned in lines 3, 4 Board of Land Surveyors or by a Decret, re-monumented, recovered, four power and range, may be recorded	in the 17-17-17-17-17-17-17-17-17-17-17-17-17-1	21 22 23 24 25 25 33 34 35 36
A Description of original	monument and accessoria	es and/or subsequent restoration	13	
		tion 1, T44N, R2W &		5N D2W
			·	- The same
Original notes	indicate a 6" (diameter fir for 1/	4 section corne	r. SE OF MICHIE
		nt restoration of the state of		* KEITH R. WATERS * LAND * SURVEYOR No. 33142
Remonumentatio Found no evide	being re-estable n Program. nce of corner.	lished as part of the Re-established corrections to the Re-established corrections and the Re-established corrections are rectally as a second correction of the Re-established corrections are rectally as a second correction of the Re-established corrections are rectally as a second correction of the Re-established correction of	ner by single p	roportionate
and common sec	tion corner 263	3.27 feet west.		(12/11/14)
C. Description of monume	ent for corner and accesso	ories established to perpetuate to	ocating the position of the	e corner:
L-13 (T45N, R2	W) 4" x 48" rebar :	with 3¼" aluminum C		
9" Spruce, N 7" Spruce, S 5" Spruce, S 8" Spruce, S	19°W 18.14' OUTH 23.25'	Note: Distances the tree. Trees a Bearings are compadeclination.	are blazed and	painted.
igned byKth_R	Water		(2-23-94	
		Date		<u> </u>
urveyor's Michigan Licens	SR MO		FORM APPROVED BY MICHIGAN STATE	BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197 REVISED JAN., 198