CONS. 4047 4/36

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_49\_NR\_7 W.\_

				-			Chipper	ra. 	COUNT	Y
DESCRIPTION	OF	CORNER	1/4 co	rner bet	ween Sec	tions.	14 and 2	3 <u>.</u>		
DESCRIPTION	OF	CORNER	MONUME	NT1"	Pipe wi	<u>th_4"                                    </u>	Brass Ca	o <b>:</b>	. <b></b> -	
WITNESSES	TO (	CORNER _	12" W. 1	Pine	<u>s 12 E</u>	68_1	Links, li	arked_"	<u>1/4 s 1</u> 18T	11
			_1 <u>8" W</u> 1	P <u>ine</u>	3 39_W_	_ 141 }	Links, li	arked <u>"</u>	1 <i>[1</i> 4_5_1 <u>1</u> BT	Ħ.
									<b></b>	

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Reg. Surveyor.

Found iron pipe and woodpost in place.

Found Tamarack 3.T. bearing S 46 W, 102 Links, in poor condition.

1/4 corner lies 12 chains East of stream.

Corner shown to us by J. Kutchera, Assistant, and L. Rubick, Aide.

Corner was placed and witnessed on 5 February 1958.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 5-19-59