CONS. 4047

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_\_50 NR\_6-7 W\_

		COUNT
DESCRIPTION	OF CORNER	Section corner common to Sections 30, 31, 25 and 36.
DESCRIPTION	OF CORNER	MONUMENT_1" Pipe with 4" Brass Cap.
WITNESSES T	O CORNER	8" Jack Pine _ 3 73 W 47% Links, (3 36 1777)
		9" Jack Pine _ S 70 E _ 38] Links, (S 31 1777)
		7" Jack Pine _ N 38 E _ 27 Links, (S 30 MBT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at site of corner tree stump. Corner tree was 6" Pine with description blaze on two sides. Tree down and splintered.

Found Pine B.T. 1 57 4, 5 Links. B.T. down and in good condition.

Found 1" Iron Pipe in place.

Corner was placed and witnessed with J. Kutchera, Assistant, and L. Rubick, Aide, on 24 June 1958.

SURVEYORS SEAL

Billy D. Buckler DATE

REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_\_\_