SURVEY & REMONUMENTATION

JAN 2 3 2001

Surveyor's Michigan License No. 39088

OHIG IS O DOG!	LAND CORNER RECORD	ATION CERTIFICA	ATE	
SECTION	Filing Requirement of Act CLARE COUNTY REMON	74, Mich. P.A. 197	70 200000009730 Filed for Record in	
For corners in			CLÁŘE CÖUNTY MICHÍGAN CAROL MCAULAY	
Clare (County)	Located In:	Corner Code #	On 11-29-2000 At 12:12 PM. LAND CORNER 9.00 OR Liber 2 Page 259 - 259	
1. Public Land Survey	T <u>17N_R_5W</u> TR	C12		
Property Controlling in Section	S T R			
3. Miscellaneous Property in Sec.	S T R S T R		H 464-00 Register of Deeds Stamp & File Nu	m.
Troporty in door				_
4. Lot No, Rec	orded Plat		A B C D E F G H I J K L M	
5. Private Claims			2 - 6 - 5 - 4 - 3 - 2 - 1 - 3	
state that under requirements of points mentioned in lines 1 and 2	a field survey on <u>July 19</u> , 20 <u>00</u> do I P.A. 74, Michigan P.A. of 1970, the corn above were in conformance with regulati	er ions	5	
and rules therefore as required in	the current manual of survey instructions Interior, Bureau of Land Management or b	of the	6 18 17 16 15 14 13	
decree of a Court of Law and /or	that the corner points mentioned in lines	3, 4	8 -19 -20 -22 -23 -24	
	e with the rules of the Michigan Board of urt of Law; established, re-established,	Lano	9	
monumented, recovered, found a	s expressed below:		10302928272625	
	-		11	
	orners, all in the same town and ran	nge, may be recorde	ed on 12 31	
this certificate.			13	
A. Description of original mo	onument and accessories and/or sub	sequent restoration	:	
C12 - GLO - Set 1/4 post-H.	Nicholson-1837		P.324-A.V. Courtright-1972;	
Beech 10" N 87	°E 25 L.		N.Sedgman-1973; 26-P.B. Lapham-1976	
Beech 9" N12°\ - CSR Rk 6, P.31a	W 31 L. &32-tile cinder & stake	L.2, P.324&34 All use 1" Pipe		
Point of large ste	one 36" NE 98 L.	7 til 400 til 1, 1, 1		
	1-A.V. Courtright-1973			
	v. Elm N45°W 34.23, 4.92, Fe. Post East 28.18			
, ,	·			
B. Description of corner evid	tence found and/or method applied	in restoring or reest	ablishing corner:	
N-S Gravel Rd. is 3.5' E. Fer Rd. cut here-not found. Sea	nce corner to west is 25.3' West. (Old Down Fence Co pears to have been	ong Iron Pipe per LCRC's & Rec. Surveys. CL of orner East is 27' + East. Search for tile but large cleared. We find many stones near E-W of the original corner.	
C. Description of monument	for corner and accessories establish	hed to perpetuate lo	ocating the position of the corner:	
	pipe w/ 4" Dept. of Conservation (End capDown 1'-w/ ring of cobbles.	ONR) Brass Cap on 1	1" x 36" Galv. Iron Pipe w/ 6" x 1' PVC	
N60°E 50.73' to set	N&T in NW Side 10" Sco. Pine		OF MA	
S52°E 40.15' to CL 2			STATE OF MICHIGA	
	N&T in N Side 13" Beech N&T in SW side 24" Tw. R. Maple	(AVC)	CRAIG W.	
	cepted in place of Clare Co. Remon.		* McVEAN * PROFESSIONAL *	
		APPROVED LAN	D CORNER SURVEYOR No. 39088	
		P.A. 345 of	1990 39088	
		Clara Col	anty ShorEssional State	
		Chairman Aud	at the	
			- ·	