SURVEY & REMONUMENTATION

JAN 2 3 2001

LAND CORNER RECORDATION CERTIFICATE

CECTION

Filing Requirement of Act 74, Mich. P.A. 1970

3501101	v Clare	e County Remonu	mentation
For Corners in Clare		·	200000010149 Filed for Record in CLARE COUNTY MICHIGAN CAROL MCAULAY
(County)	Located In:	Comer Code#:	On 12-15-2000 At 07:44 am. LAND CORNER 9.00
1. Public Land Survey	T. <u>17N</u> R. <u>6W</u> T. R. T. R.	D-13	Instrument Liber Pa
2. Public Controlling in Section	S T R S T R	·····	200000010149 DR 2 2
3. Miscellaneous			J F (, ,
* *	S T R		D
5. Private Claims	, Recorded Plat		Register of Deeds Stamp & File Number
5. Filvate Claims			
74, Michigan P.A. of 1970, the cowith regulations and rules therefore. United States Department of the Law and/or that the corner points rules of the Michigan Board of Lestablished, monumented, re-more NOTE: Not more than 2 recorded on this certifical A. Description of origin restoration: 1. G.L.O Original Survey:	al monument and accessori	2 above were in conformance of survey instructions of the t or by a decree of a Court of were in conformance with the ourt of Law, established, ressed below. In and range, may be test and/or subsequent	2 6 5 4 3 2 1 3 + + + + + + + + + + + + + + + + + + +
Pages 299 origina 2. County Survey Records None of Record 3. L.C.R.C.:	l field notes		
	5 Paul B. Lapham 1984 S		ele proportion measurement
Liber 887, Page 9 4. Surveys of Record: None of Record	9 Mark Robison 1999 I	Found ½" capped re-rod	APPROVED LAND CORNER P.A. 945 of 1990
5. Unrecorded Survey:			Clare County
Paul R. Lanham s	urvey 1984 Found 1/2" cap	ned re-rod	Chairman Accels Top
Paul B. Lapham s	urvey 1988 Found ½" cap urvey 1999 Found ½" cap	ped re-rod	Date 9-13-00
B. Description of corner ex	vidence found and/or method	applied in restoring or re-	establishing corner:
 Found capped Found wood p 	tablished in Clare County Re- iron, cap unreadable ieces laying down to the south 5.5. Original soil at 1.0. No	h of iron. Wood was at n	See dossier for detailed report.
C. Description of monume	nt for corner and accessories	established to perpetuate	replaced with Standard Monument Corner. locating the position of the corner: 3/17-6 and D-1/16-6 and PS 21567.
D-13 S. 1/4 Co S.68°W. N.15°E.	orner, Section 32, T.17NR. 57.76' Set nail and tag in N	6W., Garfield Township forth face of 4" wood fend Vest face of new power po	o, Clare Co., MI.

Found capped iron, property controlling corner East. 52.67

S.89°38'31"E 2646.12' E-13 Corner common sections 32 & 33, T.17N.-R.6W., Garfield Twp., Clare Co., MI. N.89°38'11"W. 2645.94' C-13 Corner common to sections 31 & 32, T.17N.-R.6W., Garfield Twp., Clare Co., MI.

Signed by Surveyor's