SURVEY & REMONUMENTATION

CLARE COUNTY REMONUMENTATION

JAN 2 3 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74 Mich. P.A. 1970

	Filing Requirement of Act 74, Mich. P.A	1970 37 ² 7
For corners in		
CLARE SECTION Located In	n: Corner Code #	
2. Property Controlling S	T 17N R 5W T 17N R 6W T R T R T R	19 19 19 19 19 19 19 19 19 19 19 19 19 1
in Section S	TR	
3. Miscellaneous S S Property in Sec. S	'R T R	
1 Toperty 11 Oec		Register of Deeds Stamp & File Number
A Lakkia		
4. Lot No, Recorded Plat 5. Private Claims		ABCDEFGHIJKL
***************************************		2 6 5 4 3 2
		3
, MARK R. ROBISON , in a field s	survey on $\underline{Dec. 15}$, 19 $\underline{97}$ do hereby state that un	nder 4 - 7 - 8 - 9 - 10 - 11 - 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the		re in
United States Department of the Interior, Bureau	J of Land Management or by a decree of a Court of Law and	d/or 6 10 17 16 15 14 17
Board of Land Surveyors or by a Decree of	nd 5 above were in conformance with the rules of the Michi a Court of Law; established, re-established, monumen	gan 7
recovered, found as expressed below:	,	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the	same town and range, may be recorded	9
on this certificate.		10 30 29 28 27 26 25
		11
		12 31 32 33 34 35 36
A Depoription of original manufact and	accessories and/or subsequent restoration:	13
1837 Hodgson Set Post at 79.47 WitTamarack 12 N52W 12 Cedar 14 S42W 23	5-1-72 Lapham-LCRC#24 1/2" iron WitN30W 43.23 Spike 6" Cedar N30E 33.10 Spike 10" Cedar S50E 65.80 Spike 4" Cedar	9-14-81 Robison-PBL Files (unrecorded survey) Found 1 1/4" Pipe in 3" tile Witsame as LCRC#24
circa 1900-CSR 6-31	S45W 43.30 Spike 8" Cedar	1996 Robison-PBL Files-Found Sucker Rod
WitCedar 6" NE 3 1/2 Cedar 5" SE 5	9-5-73 Sedgman (132)1-574 - Ref LCRC#24 Meas. North 2621.09 to A-12	
	1978 Lepham-Fd 1 1/4" pipe in 3" tile Wit-same as LCRC#24 (unrec survey)	N50W 19.8 N&T in 5" Cedar S45W 17.41 N&T in 6" Cedar
B. Description of corner evidence found	and/or method applied in restoring or reestablishing	
Found 5/8" x 36" sucker rod in broken clay	ville. Found 1 1/4" x 30" pipe leaning and driven sligh I as corner. Old witnesses fit rod in broken tile.	
		APPROVED LAND CORNET
	•	P.A. 945 of 1999
See dossier for detailed report.		Clery Pounty
		Chalman fauls 1910
		Dalo 12-73-91
C. Description of monument for corner ar	nd accessories established to perpetuate locating th	he position of the corner:
A-13: Set 1/2" x 24" Aluminumm rod with accepted position of the corner.	Isabella County Remonumentation Cap marked P.S.f	#27458. Accepted as best available evidence of the
Wilnesses:		
N40E 33.60', nail & tag, 12" Cedar (OBT) N60W 19.80', nail & tag, 5" Cedar (OBT)		Walter Control of Market
\$52W 17 41', nail & tag, 5" Cedar (OBT)		AGI processor and the
\$40E 65.5', nail & tag, 7" Cedar (OBT)	-	The second of th
$\sim 10^{\circ}$	′ .	
Mr. () (/a)	2,5,	
Signed by M/MW . (OP)	2/ > / Date	12-22-97
Surveyor's Michigan License No. 27	458	