JAN 1 4 1999

CLARE County Remonumentation

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

18 DEC 29 PH 3: 04

REGISTER OF DEEDS CLARE COUNTY CAROL A. MOAULAY

legister of Deeds Stamp & File Number

	Filling Redonation		, 9
For corners in			, , , , , , , , , , , , , , , , , , ,
_CLARE	Located in:	Corner Code #	1
(County)			C
1. Public Land Survey	T <u>18N_</u> R	<u>03W H-5 </u>	
	Τ <u></u> R τ Β		
	1		
2. Property Controlling	s TR		
in Section	S TR		
Miscellaneous Property in Sec.	S \		R
Property in Sec.	- <u></u>		
			a
4 Lot No, Reco	orded Plat		- A

5. Private Claims I. Mark R Robison , in a field survey on October , 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigans that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigans Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

10 13

A. Description of original monument and accessories and/or subsequent restoration:

4. Lot No.

H-5: 1856 Cannon S89-30W 39.53, 1/4 Corner in Lake

39.81 over Lake Trigonometrically & set witness post Tamarac \$57-1/2W 83

1911 Johnson, CSR 4-51 Tamarac 7 S57-1/2W 85 Tamarac 8 N84W 136 Gov't, Tree

1909 Johnson, CSR 5-159; Same as above

1996 McVean, LCRC #820; See detailed description on LCRC. Corner in Lake not set. S.P. position is witnessed as follows: \$89 48 54 W, 100.00' 2" AC on Sec. line N89 48 54 E 366.10 4" PAS. B. C. on R1W & Sec. line N89 48 54 E 723.98 4" PAS. B. C. on R1W & Sec. line N0 28 02 W 1138.58 4" PAS. B. C. on shore-line & NS 1/4 line

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
H-5: H- 5 falls in Lake. Found D.N.R. witness monument 100 feet West of Corner and D.N.R. monument 366.10 feet East of Corner. (Both are on Section line). Set two more witnesses to corner in take. Also witnessed the D.N.R. monument to the West share of the lake as: monument on the West shore of the take as: S30E, 18.16', N & T in P.P. S87W, 29.04, N & T in 2" triple Cedar

See dossier for detailed information

S56E, 73.36, N & T in top center of end guard rail post C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Description of monument for corner and accessories established to perpetuate locating the position of H-5: Corner falls in take. S.P.M. position is accepted as best available evidence of the correct position of the corner. Section line bearing is S89°48'54" W. S89°48'54" W. 100.00', 2" D.N.R. monument (OBT) N89°48'54" J. 386.10', 4" D.N.R. monument (OBT) S80°39'04" W, 91.17', Nail & Tag in P.P. S43°39'57" W, 58.12', Nail & Tag in top center end gaurd rail post

TE OF WICH

ROBISON

APPROVED LAND CORNER P.A. 345 of 1990

Clare Odunty

Chairman 10 Date 12-08-98

12-23-98 Date

X LICENSER Signed by Manu (27458 Surveyor's Michigan License No.

PROFESSIONAL SURVEYOR No. ., 27458 POFESSION The state of

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995