SURVEY & REMONUMENTATION

JAN 2 3 2001

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION	Clare	County Remonume	entation		
For Corners in Clare			Filed CLARE CAROL	0010177 for Record in COUNTY MICHIGAN MCAULAY	
(County)	Located In:	Corner Code#:	LAND C	15-2000 At 07:44 am. CORNER 9.00	
1. Public Land Survey	T18N_R3W TR	I-6	OR Lib	er 2 Page 300 – 30 strument Liber F	
2. Public Controlling S.	T R T R		2000	000010177 OR 2	300
in Section S.	T R T R		#50	15-00	
4. Lot No,			Register of I	Deeds Stamp & File Number	
5. Private Claims				soon stamped the Number	
conformance with regulations and rul instructions of the United States Depi decree of a Court of Law and/or that conformance with the rules of the Mi Law, established, re-established, mon below. NOTE: Not more than 2 cor recorded on this certificate. A. Description of original n restoration:	artment of the Interior, Bureau of the corner points mentioned in lir chigan Board of Land Surveyors numented, re-monumented, recover ners, all in the same town	Land Management or by a les 3, 4 and 5 above were in or by a Decree of a Court of cred, found as expressed and range, may be	5 10 17 7 8 19 20 9 1 1	-4 - 3 - 2 - 1	
GLO, Cannon, 1856 Existir	ng Post				
W. Pine 24" N73 1/2°E 32 LINKS		C.S.R. Johnson, 19		4 & Bk. 5 Pg. 51	
W. Pine 22" S76°W, 18 ½ I	LINKS	1-6 to $H-6 = 40.135$			_
I-6 to I-5 = 40.29 chains I-6 to I-7 = 40.49 chains		I-7 to $I-6 = 40.17$ c	hains	APPROVED LAND CORNI P.A. 345 of 1990	æ
		Lapham, 1971. LCI	RC #13-71	Clare County	
C.S.R. Johnson, 1907, Bk 4	. Pg. 125	4 witnesses		Chairman Sould lot	
I-6 to J-6 = 40.265 chains I-6 to K-6 = 80.54 chains		Survey, Urbaniak, 1	1971 not record	leans 12.13.00	
		Same as LCRC #13-7 I-6 to I-5 = 2633.5	1		
		Set from found center Section 14. This loca position between I-5	tion is very near	single proportionate measure	
B. Description of corner eviden	nce found and/or method a	oplied in restoring or re-est	ablishing corner.	•	
No GLO or CSR evidence of cand I-7 at record distance (263 evidence of re-established CSR C. Description of monument for	3.5') from I-5, found witner Position of corner. Position	ss matches re-established con is 9 feet North of center	orner). Accepted line road to East	ner from 1971 survey (on line between the details and fits G.L.O. proration.	veen I- ble

Set 5/8" x 36" rerod with Clare County Remon Cap marked P.S. #27458 Witnesses:

S06°E, 106.29' - N & T in Utility Pole (OBT)

\$38°E, 61.04' - N & T in Fence Post

Surveyor's Michigan License No.

S80°E, 128.94' - N & T in 11" Elm

N85°E, 72.66' - Top of west end of 12" CMP