## SURVEY & REMONUMENTATION

JAN 2 3 2001

## LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

**Clare County Remonumentation** 

(County)		Located In:	Corner Code#:	
1. Public Land Survey		T. <u>18N R. 5W</u> T. <u>18N R. 6W</u> T. R.	A-5 M-5 1	
2. Public Controlling in Section	S S	T R T R		
3. Miscellaneous Property in Section 4. Lot No	S S , Rec	T R T R corded Plat		

ON
200000010143
Filed for Record in
CLARE COUNTY MICHIGAN
CAROL MCAULAY
On 12-15-2000 At 07:44 am.
LAND CORNER
2022 266 --2 Page OR Liber 266 -266

Liber Page 2000000010143 OR

12

13

24

25

36

a471-00

18

19

31

10 30 17

20

29

- 16

21

28

33

Register of Deeds Stamp & File Number

ABCDEFGHIJKLM

10 11

15

22

27

34

-14

23

26

35

I. Mark R. Robison, in a field survey on May 19, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

This is a single corner common to T18N, R5W, & T18N, R6W.

A. Description of original monument and accessories and/or subsequent restoration:

GLO

Lyon, 1848

Beech 10" N57°W, 10 LINKS Beech 10" S43°W, 12 LINKS

Beech 10" S33°E, 16 LINKS Maple 6" N43°W, 38 1/2 LINKS

C.S.R, Harper, 1902, Bk 1. Pg. 12

& Bk. 4 Pg. 14

W. Pine Stub 20" S18 1/2°W, 47 LINKS

W. Pine Stump 18" N27°E, 75 LINKS

Lapham, 1992 LCRC #669-92 Found P.K. Nail, 4 witnesses

Lapham, 1995, LCRC #770-95 Found P.K. Nail, 4 witnesses with 2 the same as LCRC #669-92

Survey, Robison, 1993 L3. Pg. 477

Same as LCRC #770-95

B-5 to A-5 = 2544.94 (GLO = 2514.6)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

No evidence of GLO survey found. Found spike and excavated to 2' and found nothing else. Found 3 witnesses from LCRC #770-95 with I in good shape. Measured to B-5 as 2544.58' to A-4 as 2636.77', to A-6 as 2622.67' and to L-5 (18N6W) as 2663.88'. Corner is 5' South of centerline East-West road (Mannsiding) and on centerline road to South (Hemlock). No evidence of another corner found. Accepted found spike as best available evidence of position of corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8"x 36" rerod with Clare County Remon Cap marked P.S. #27458 in Monument Box.

Witnesses:

N55°W, 45.95' - Center of telephone riser (OBT)

N45°E, 53.76' - N & T in Fence Post

S63°E, 74.58' - N & T in Power Pole

S48°W, 49.94' - N & T in 17" Balsam

MARK R. ROBISON PROFESSIONAL SURVEYOR No. 27458

APPROVED LAND CORNER

P.A. 345 of 1990

Clare County

Signed by Date OF ESSIONS Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983