LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

••••	ອ	•	 ۹.	••••	٠.		•••	-	٠.	•		•	٠,	
	_		١,	.11	1	R)		ĸ	īŦ	•	T		N.	

REMONUMENTATION									
For Corners In: Clare	Located In Corner Code #								
(County)									
1. Public Land Survey	T 19N R 6W F3								
Property Controlling in Section	S T R R								
Miscellaneous Property in Section	S T R S T R Register of Deeds Stamp & File Number								
4. Lot No:	Recorded Plat: A B C D E F G H I J K L M								
5. Private Claims:	2 6 5 4 3 2 1								
requirements of PA 74, Mic and 2 above were in conforthe current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established,	eld survey on Aug. 28, 2008 do hereby state that under thigan PA of 1970, the corner points mentioned in lines 1 mance with regulations and rules therefore as required in vey instructions of the United States Department of the nagement or by a decree of a Court of Law and/or that the lines 3, 4 and 5 above were in conformance with the rules Land Surveyors or by a Decree of a Court of Law; monumented, recovered, found as expressed below: 2 corners, all in the same town and range, may trifficate.								
Thence S85°30'W - 1992 – LCRC #657 After an extensive meander corner, I location of corner. Sec. Cor. And the GLO, from that posto set the corner.	40.82 to section corner -92, Robert L. Wetherell search for the original corner, witness trees and was unable to recover any evidence as to the I took the straight line distance between the SW. SE. Sec. Cor and prorated this distance with sition I went north 164.08'(as measured by GLO) evidence found and/or method applied in restoring or re-establishing corner:								
pipe at single prop GLO survey had "f line. East to 22' to meander corner w S85°51'13"W 2674	to Section 4 and 9, T19N, R6W – No GLO evidence – Set 4" stamped DNR Alum. Cap on 1" x 4' long gall ortion position to GLO using the record GLO angle between 'E3' and reestablished 'G3'. Calculated that the "3" – 107.5' North of a straight line between 'E3' & 'G3'. This solution places 'F3' – 106.71' North of said stated bottom of Bank and W. Edge of Old River Channel. River eroded West greatly since 1856 since the Right as 2.44 Chains East. West 21' to Top of High Bank. Measured Grid Bearing and distance as follows: 1.42' (S85°30'W 2694.12' – GLO) to 'E3' and S89°29'47"E 2587.95' (S89°51'E 2607' – GLO) to 'G3'. DNR and as a careful and faithful reestablishment of the position of the original corner.	ne traigh it banl							
 <u>Reference Pt.</u> – Notes on rejected 'G3' point as 'F3' in this surve 	51°51'W 12.55' from 'F3' found 5/8" iron in 4" concrete monument per Wetherell LCRC. This monument is sistion and incorrect straight line offset distance between corners east and west. Concrete Monument not bey.	base utilize							
C. Description of monun	nent for corner and accessories established to perpetuate locating the position of the corner:								
and around monun Set Blue Carsonite N50°W 38.70' to fd N21°W 31.64' to se									

N50°W 38.70' to fd. Nail in SW side 17" Oak (#3)
N21°W 31.64' to set Nail & Tag in E. side 8" Oak scribed 'XBT'
N52°E 3.68' to set Nail & Tag in SE side 9" Cherry scribed 'XBT'
S60°W 40.77' to fd. Nail in SE side 10" Oak scribed 'XBT'
N51°51'W 12.55 to Reference Pt. — Concrete Mon. MCVEAN PROFESSIONAL SURVEYOR No. 39088 Signed by: Cruy W. Me Ver Surveyor's Michigan Lieense No.: 390 PROFESSION Date:

CRAIG W.