SURVEY & REMONIMENTATIO

MAR 24 2000

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

(County)	(County)		d In:	Corner Code#
1. Public Land Survey		T. <u>19N</u>	I_R. <u>3W</u>	<u>I-13</u>
		T	_ R	<u></u>
		T	-	
2. Public Controlling	S	Т	_ R	
in Section	S	T	_ R	
3. Miscellaneous	S	T	_ R	
Property in Section	S	T	_ R	
4. Lot No	, Rec	orded Pla	at	
5. Private Claims				
<u> </u>				

199900010468
Filed for Record in CLARE COUNTY MICHIGAN CAROL MCAULAY In 12-03-1999 At 02:36 pm. AND CORNER 9.00 2 Page OR Liber 106 -106

Instrument Liber Page 199900010468 DR

#394-99

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on April 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1838 Nicholson Set Post Cor 34-35

All Standard Corners on the South line of T19N, R3W, were established in 1838. In 1856 the Closing Corners for T18N, R3W, were recovered in a GLO resurvey. The MSHD survey notes of 1933 state that the corners used in that survey are the T18N, R3W Closing Corners. The MSHD right-of-way maps indicate that the Standard and Closing Corners are common (which they are not). All evidence of the original corners has been destroyed in highway construction. The preserved monumented corners have been used as both T19N & T18N, R3W, common corners in most subsequent surveys. Although not conclusive, farm fence lines south of this tend to support the

2 8 10 11 12 18 17 16 15 14 13 19 24 20 21. 22 23 10 30 29 28 26 25 -27 36 34

monuments as Closing Corners. The 1856 resurvey of T18N, R3W, states that along with A-1 & M-1, B-1, & C-1 are also common with corresponding T19N, R3W, corners. In this remonumentation program, all lost Standard Section Corners have been established at the recorded G.L.O. distances from the Closing Corners and all lost Standard 1/4 Corners have been established at S.P.M. between section corners.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: See dossier for detailed report.

Found I-1, T18N, R3W. Set corner on section line at G.L.O. falling 27.06 feet East of Closing Corner I-1 on line H-13/I-1 extended East 27.06 feet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 36" rerod with Clare Co. Remon Cap marked P.S. #27458 in Mon. Box. Accepted as best available evidence of the accepted method of re-establishement of the corner.

Witnesses

N45°W, 33.65 N & T in Guard Rail Post North 22.75 N & T in Guard Rail Post N50°E, 33.90 N & T in Guard Rail Post S25°E, 28.60 C.I. - G.P.S. #18 at back of curb West 27.06 Closing Corner I-1

APPROVED LAND CORNER

P.A. 345 of 1990 Clare County

Chairman Hau

Dais 12-08-98

ROBISON **PROFESSIONAL** SURVEYOR

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983

Surveyor's Michigan License No.

OFESSION