MAR 24 2000

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in			199900010473 Filed for Record in
Clare (County)	Located In:	Corner Code#:	CLARE COUNTY MICHĪĠAN CAROL MCAULAY
, ,		ļ	On 12-03-1999 At 02:36 pm. LAND CORNER
1. Public Land Survey	T. <u>19N</u> R. <u>3W</u> T R	J-13	on cross. I page III . III
	T R		Instrument Liber Page 199900010473 OR 2 111
2. Public Controlling in Section	S T R S T R		133300010475 OK E 111
3. Miscellaneous	S T R		- 200 .00
	S R		#399-99
4. Lot No 5. Private Claims	_, Recorded Plat		Register of Deeds Stamp & File Number
5. Private Ciaims			
P.A. 74, Michigan P.A. of 1970, the conformance with regulations and instructions of the United States Decree of a Court of Law and/or the conformance with the rules of the Law, established, re-established, in below.	ey on April 1998, do hereby certifue corner points mentioned in lines rules therefore as required in the corepartment of the Interior, Bureau of the corner points mentioned in li Michigan Board of Land Surveyors nonumented, re-monumented, recoverence, all in the same town e.	1 and 2 above were in urent manual of survey f Land Management or by a nes 3, 4 and 5 above were in or by a Decree of a Court of ered, found as expressed	1A B C D E F G H I J K L M 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5 1 1 1 1 12 6 18 17 16 15 14 13 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
A. Description of origina restoration;	l monument and accessori	es and/or subsequent	Communication of the second section of the section of the second section of the section of the second section of the sec
1838 Nicholson			APPROVED LAND CORNER P.A. 345 of 1990
Set post S1/4 Cor Sec. 35			Clare Qounty
1903 Johnson Stake J-13 to I-13 40.00			Chairman faull toph
CSR 1-23 and 4-30			Chairman faults type Daie 12-08-98
Undated - Unknown Elm 10, S63 ½ W 100 ½ CSR 5-107			
All Standard Corners on the So of T19N, R3W, were establish 1838. In 1856 the Closing Cor T18N, R3W, were recovered in resurvey. The MSHD survey in 1933 states that the corners use that survey are the T18N, R3W Closing Corners. The MSHD	ed in Standard and ners for common (where a GLO evidence of the least of leas	maps indicate that the Closing Corners are ich they are not). All he original corners has ed in highway The preserved corners have been used & TI8N, R3W, hers in most subsequent hough not conclusive, farm ath of this line tend to	Corners. The 1856 resurvey of T18N, R3W, states that along with A-1 & M-1, B-1 & C-1 are also common with corresponding T19N, R3W, corners. In this remonumentation program, all lost Standard Section Corners have been established at the recorded G.L.O. distances from the Closing Corners and all lost Standard 1/4 Corners have been established at S. P.M. between section corners.
See dossier for detailed repo	dence found and/or method a rt.		•
C. Description of monument Set 5/8" x 36" rerod with Clare-establishment of the corne	(MSHD 2617.35) to 1-1. Con for corner and accessories eare Co. Remon Cap marked I	mer falls on fence line to N stablished to perpetuate loc	13 T19N, R3W. Meas. East 2635.82 (MSHD 2638.70) to lorth. cating the position of the corner: Accepted as best available evidence of accepted method of
Witnesses: S40°E, 29.99 N & T in Top Cen. of Guard Post			
S57°W, 32.76 N & T in Top Cen. of Guard Post N30°W, 27.15 N & T in Top Cen. of Guard Post			
N42°E, 23.85 N & T in Top Cen. of Guard Post PROFESSIONAL PROFESSIONAL			
East 23.65 Closing Corner Signed by	Ann O. Case	SURVEYOR No.	Date 12-3-99
Surveyor's Michigan License No. 27458 27458 PRIAPPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971			
-	-	POFESSIONA	REVISED MAY 14, 1978
			REVISED JAN., 1983