SURVEY &	
REMONUNENTATION	

RECEIVEL

FEB 1 8 1994

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1993 DEC 20 PM 1: 48

	corners	9000	ħ.Á	MA	1				ؠؙٚٷ
For	comers	in Carl	188	1 W E	3	44.5 4.54	7 .	,	

Property in Sec.

CLARE Located In: Corner Code ## 19N R 4W G-10 **Public Land Survey** __ R **Property Controlling** __ R . _ R _ in Section _ T _ ___ T ____ R _ Miscellaneous

T

REGISTER OF DEEDS CLARE COUNTY DONNA M. CARR

Register of Deeds Stamp & File Number

Lot No. ____ , Recorded Plat _ Private Claims _

_ R _

MARK R. ROBISON NOVEMBER in a field survey on I. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: 1856 G.E. ADAIR, POST - W. OAK 4" N 19°W, 16 LKS 370 W. OAK 5" S 81-3/4°E, 28 LKS 9-7-13 A. JOHNSON, PINE 24" S 53°E, 44 LKS CSR 1-31 12-26-72 M. McCLUNG, FOUND IRON LCRC 79-72 7-24-73 LAPHAM LCRC 79-72 11-29-76 SEDGMAN LCRC 258-76

	Α	В	Ç_	D	E	F	G	н	<u> </u>	K	Ļ	M
2		6		5—		4		3 —		2		
3	<u> </u>	$oxed{oxed}$	辶			_		`		ļ <u>.</u>		
4		 7—	L	! 8—	L.,	ļ —	L	 0—-	1	 1—	1	2
5	_		_			_	_		<u>_</u>	_		
6	L	8—	ļ	 7	L,	[6—-	1	 5—	┝	4	Ļ	3—
7	_		ļ	ļ	ļ	<u> </u>	_	_	ļ	_		-
8	<u> </u>	! 9—	 - ;	 20	2	 !1—	<u> </u> -2	! 22—	-2	3—		4
9	<u> </u>	<u> </u>	_		<u> </u>	<u> </u>	ļ	<u> </u>	-	_	_	
10	Ļ	30	-	 29—	<u> </u> -2	 :8—	-2	 27—	<u> </u> -2	 6	<u> </u> -2	5
11	\vdash	-	lacksquare	-	!	_	<u> </u>	<u> </u>	_			-
12	Ļ	 31—	ļ;	 32	Ļ	 33—	L	 34—-	 	5	_ 3	6-
13		1			L	L	1					

Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 1/2" x 18" RE-ROD OVER 5/8" x 15" BAR. EXCAVATED TO 36" DEPTH, FOUND FOUND RECORDED WITNESSES:
N 20°W, 71.23' — POWER POLE
N 50°E, 57.22' — POWER POLE
S 10°E, 10.2.35' — POWER POLE

x 18" RE-ROD OVER 5/8" x 15" BAR. EXCAVATED TO 36" DEPTH, FOUND NO OTHER EVIDENCE.

10°E, 102.25' - POWER POLE

This Corner established in Clare County Remonumentation Program. See dossier for detailed report.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Description of monument for corner and accessories established to perpete SET 5/8" X 36" RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP.

N 20°W. 71.21' — POWER POLE
N 50°E, 57.33' — POWER POLE
S 10°E, 102.38' — POWER POLE
S 25°W, 40.50' — U.G. CABLE MARKER (3" PIPE)
S 60°E, 53.29' — N.W. COR. BLOCK BLDG.



MARK ROLL

_ Date _

Surveyor's Michigan License No. _

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAH., 1983