BUTTYEY & BEMONUMENTA.

## **CLARE COUNTY REMONUMENTATION**

NOV 1 8 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REC	j	ĺΝź	<b>\$</b> ::	1
		•	-	

For corners in COMMIS	SION		# 204-97
CLARE (County)	Located In:	Corner Code #	97 OCT 15 AH 10: 49
1. Public Land Survey	T <u>20N</u> R T <u>19N</u> R TR		REGISTER OF DEEDS CLARE COUNTY CAROL A. MOAULAY
Property Controlling     in Section     Miscellaneous     Property in Sec.	TR S T R S T R S T R		FRAHKIN HAMILTON  Register of Deeds Stamp & File Number
4. Lot No, Reco 5. Private Claims			A B C D E F G H I J K L  2 6 5 4 3 2 1
requirements of P.A. 74, Michig conformance with regulations and United States Department of the that the corner points mentioned	an P.A. of 1970, the corne d rules therefore as require Interior, Bureau of Land M d in lines 3, 4 and 5 above	July 1, 19 97 do hereby state that er points mentioned in lines 1 and 2 above and in the current manual of survey instruction lanagement or by a decree of a Court of Law were in conformance with the rules of the More Law: established, re-established, monur	were in 5

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

1838 Nicholson Set 1/4 Sec. Post Wit-Elm 8" N83W 55 Lynn 10" N74E 40 6-28-07 Johnson CSR 4-110 Wit.-Pine Stump 40 N78 1/2W 194 Fence Post 8" S46 1/2W 53 4-25-08 Johnson CSR 4-136 Wit.-same as CSR 4-110 Notes all Gov't Cor.'s found

recovered, found as expressed below:

on this certificate.

**Undated CSR 5-73** Wit.-Pine Stump 40" N78 1/2W 194
Fence Post 8" S46 1/2W 53
Pine Stump 28" S31 1/2E 58 1/2
3-15-73 Urbaniak (132) 1-431
Wit.-NE 80.7 NW Cor Bridge SE 70.4 SW Cor Bridge South 121.8 NE Cor Bridge 4-05-73 Urbaniak LCRC#96 Est. from Co. Rd. Witnesses Wit.-same as (132) 1-431

4-25-73 Urbaniak (132) 1-486 Wit.-same as (132) 1-431 4-18-90 Wilcox LCRC#600 Set 1/2" rebar w/cap Wit.-N05E 31.15 10" Elm N70E 61.69 P.P. **S60W 77.80 Fence Post** \$50E 65.25 4" Elm

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" x 18" rerod in monument box in centerline of T-road South. Excavated and found no other evidence. Found all 1973 witnesses and two 1990 witnesses. Measured South 2725.95 (Recorded 2725.94) to L-2, T19N, R3W, per (132) 1-431. Measured East 2628.49 to M-13. Measured West 2669.44 to K-13. Fence line to North. Measured East 80 ft. to stream (GLO 165 ft.). GLO topo notes appear to be in error, i.e. stream does not fall in swamp and is well defined with high banks on both sides. Arnold Lake Road underwent major reconstruction in the 1990's. Old Corners destroyed during construction were to be perpetuated by Wilcox, County Engineer.

APPROVED LAND CORNER P.A. 345 of 1990 Clare County

See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set 5/8" x 36" rerod with Clare County Remonumentation Cap marked P.S.#27458 in Monument Box. Accepted as best available evidence of the accepted position of the corner.

Witnesses: N05E 31.15', N&T, 13" Elm (OBT) S68W 77.80', N&T, F. Post (OBT) S16E 44.88', N&T, Top Guard Post

N41E 25.60', N&T, Top Guard Post

Signed by Surveyor's Michigan License No. Date 10-01-9