## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970
Clare County Remonumentation

	Clare County	y Remonumen	tation	
For Corners In:	Located In Corr	ner Code #		
(County)  1. Public Land Survey	T 20N R 3W C	C3		
Property Controlling in Section	T R S T R S T R			
Miscellaneous     Property in Section	S T R S T R		Register of De	eeds Stamp & File Number
4. Lot No:	Recorded Plat:		ABCDE	- G H I J K L M
5. Private Claims:			2 - 6 - 5 - 4	3 1 1
requirements of PA 74, Mi and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board o	field survey on Aug. 11 2003 do hereby stachigan PA of 1970, the corner points mention or mance with regulations and rules therefore revey instructions of the United States Department or by a decree of a Court of Law a lines 3, 4 and 5 above were in conformance of Land Surveyors or by a Decree of a Court of Law and Surveyors or by a Decree of a Court of Land Surveyors or	aned in lines 1 as required in artment of the and/or that the with the rules Court of Law;	3 4 - 7 - 8 - 9 5 6 -18 - 17 - 11 7 8 -19 - 2021	5
NOTE: Not more than 2 corners, all in the same town and range, may			9 30 29 2	82525
be recorded on this ce		11		
			12 31 32 3:	35 36
A. Description of origina	I monument and accessories and/or sub	sequent restorati		
C3 - GLO - Set ¼ post - G.E. Adair -1856 W. Pine 10" N65°E 13 L. W. Pine 8" S46°W 24 L. - CSR- L. 3, Pg. 56- W.S, Moore -1956- monument set 10" Oak N40°E 52.6'; Tw. Oak S51°E 44.7' - LCRC- #34-72 (L. 1, Pg. 67) - P.B. Lapham - 1972 S45°E 44.60'- tw. Oak N45°E 52.6' -10" Oak		- LCRC # 146-74 (L.1, Pg.291)- J.H. Granger – 1974 found iron; Tw. Oaks S45°E 44.6' 10" Oak N45°E 52.6' - Rec. Sur L. 1, Pg. 157 – J. Sedgman – 1972 – same wits - Rec. Sur. L. 1, Pg. 687- J.H. Granger - 1974 - Unrecorded survey – North Central Sur. Co. – project# 78350- L. Cavanagh – 1979 – 9" W. Oak S45W 31.45' 9" Maple S85°E 32.95' 12" tw. W. Oak S45°E 43.6' 12" W. Oak N45°E 52.2'		
B. Description of corner	evidence found and/or method applied in	n restoring or re-e	establishing corner:	
Remains of fence Fence line to East 42'+/- West of do	on to Sec. 5, 6, 7 & 8 - Found ¾" iron pipe to east. Moore appears to have establist. Proportionally to GLO based on recovuble proportion position. Searched in DF best available evidence of the position of	ished this position vered corners 1 n position but notl	n at the record GLO dist nile N, S, E & W, Moore hing found. Based on u	ance East of 'A3' in line with old 's position is 79'+/- North and
C. Description of monun	nent for corner and accessories establish	hed to perpetuate	e locating the position of	the corner:
C3 - Drove 3 ¼" Clare Set orange Carso S47°E 31.72' to s S41°E 44.01' to s S76°E 33.11' to s	Co. Remon. Alum Cap on 5/8" X 34" rel	par into center of ( (WSM, PBL, JH .C)	found pipes. Added ring G, JS, LC) ,LC)	CRAIG W. McVEAN PROFESSIONAL SURVEYOR No.
	ming W, Me Vain	— Date:	8/27/2003	39088 SESSIONAL
Surveyor's Michigan	License No.: 39088		•	