SURVEY & REMONUMENTATION

JAN 2 3 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Clare County Remonumentation

For Corners in			200000010165 Filed for Record in
Clare		1	CLARE COUNTY MICHIGAN
(County)	Located In:	Corner Code#:	On 12-15-2000 At 07:4 LAND CORNER 9.00
1. Public Land Survey	T. 20N R. 5W	C-9	OR Liber 2 Page 2
•	T R T R		Instrument 200000010165 OR
2. Public Controlling			
in Section	S R		
3. Miscellaneous	S R		#493-00
Property in Section	S R		
4. Lot No	, Recorded Plat		Register of Deeds Stamp & File
5. Private Claims			
requirements of P.A. 74, Michi were in conformance with regu instructions of the United State decree of a Court of Law and/o	survey on November 9, 2000, do hereligan P.A. of 1970, the corner points mulations and rules therefore as required as Department of the Interior, Bureau our that the corner points mentioned in lithe Michigan Board of Land Surveyors	entioned in lines 1 and 2 above in the current manual of survey of Land Management or by a ines 3, 4 and 5 above were in	1ABCDEFGHIJKLN 2 6 5 4 3 2 1 3 +
	1		6-10-17-16-16-14-12

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Adair, 1856

Set Post

helow

S. Pine 9" S22 1/4°E, 9 LINKS

Survey, Lapham, 1971, Unrecorded C-9 to D-9, 2634.7

LCRC, Lapham, 1983 LCRC #441-83

C-9 to E-9, 5259.5

Found sucker rod

Four witnesses

CSR, Johnson, 1935

Bk 2. Pg. 70 Two witnesses

C-9 to A-9, 77.50 chains

CSR, Johnson, 1935

Bk 2, Pg. 68

C-9 to E-9, 79.90 chains

LCRC, Roser, 1992

Found sucker rod & two 1983 witnesses

CSR, Lapham, 1960 Bk 3. Pg. 115 Iron, two witnesses

LCRC #722-92

Four witnesses and location of roads, E, N, & S

4 am. 88 -288

Liber Page 288

e Number



Survey, Roser, 1994, Unrecorded Same as LCRC #722-92 C-9 to B-9, 2608.03 C-9 to D-9, 2634.60

APPROVED LAND CORNER P.A. 345 of 1990

Clare County

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

Found sucker rod and two 1983 witnesses and all 1992 witnesses. Did not find any other witnesses. Verified DNR distances to B-9 and D-9. Accepted sucker rod as best available evidence of the position of the corner. Corner is 3' East of centerline road South and 4' South of centerline road East.

MARK R.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" rerod with Clare County Remon Cap marked P.S. #27458.

Witnesses:

N60°W, 49.60' - Fd spike in 15" R. Pine (OBT)

N15°E, 28.43' - Fd spike in 12" R. Pine (OBT)

N60°E, 51.95' - Fd spike in 10" R. Pine (OBT)

S50°W, 55.21' - Fd spike in 12" Twin R. Pine (OBT)

ROBISON **PROFESSIONAL** SURVEYOR

Date

Surveyor's Michigan License No.

TATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983