## SURVEY & REMONUMENTATION

JAN 2 3 2001

## LAND CORNER RECORDATION CERTIFICATE

## SECTION

Filing Requirement of Act 74, Mich. P.A. 1970 **Clare County Remonumentation** 

For Corners in			rited for Record in
Clare			CLARE COUNTY MICHIGAN CAROL MCAULAY
(County)	Located In:	Corner Code#:	On 12-15-2000 At 07:44 am. LAND CORNER 9.00
1. Public Land Survey	T. <u>20N</u> R. <u>5W</u>	E-9	OR Liber 2 Page 286 - 28
	T R T R		Instrument Liber 200000010163 OR 2
2. Public Controlling	S R	*	200000010163 OR 2
in Section	S T R		± 491-00
3. Miscellaneous	S R		T 441.00
Property in Section	S R		
4. Lot No	, Recorded Plat		Register of Deeds Stamp & File Number
5. Private Claims			
			ADCDEECHLIVIM
	urvey on November 28, 2000, hereby		
of P.A. 74, Michigan P.A. of P.	970, the corner points mentioned in Iir	ies i and z above were in	2: 6   -5 4 2   2   1

conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1 7 8 10 12 5 6 18 17 16 15 14 13 19 20 21 22 23 24 9 10 30 29 28 25 27 26 11 12 31 32 33 34 35 36

200000010163

286

Page

286

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Adair, 1856

Set Post with two witnesses

CSR, Unknown, 1914

CSR Bk 6. Pg. 130, two witnesses

E-9 to E-7 = 80.34 chains

CSR, Johnson, 1935

CSR Bk 2. Pg 76, two witnesses

E-9 to G-9, 80 chains

E-9 to Pond East, 26 chains

CSR, Johnson, 1935

CSR, Bk 2. Pg. 68, two witnesses E-9 to C-9, 79.90 chains

LCRC, Lapham, 1992 LCRC #675-92

Found 1/2" Iron

Four witnesses

LCRC, Roser, 1992

Fd 1/2" rerod w/1 1/4" x 3/16" strap iron beside it.

Four witnesses and cedar post

Plat, McClung, 1966 - Howard Heights Subd, L8. Pg. 31

Plat, Lapham, 1968 - Howard Heights Subd #2, L9, Pg. 4

Plat, Lapham, 1975 - Howard Heights Subd #3, L14. Pg. 38

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

Found 1/2" rerod and strap iron over large chunks of metal surrounding a State of Michigan Monument cap broken off a 3/4" x 18" pipe. Verified one 1935 witness and all 1992 witnesses. Verified distance E-9 to D-9 and F-9 by G.P.S. Accepted 3/4" pipe & 1/2" rerod as best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" rerod with Clare County Remon Cap marked P.S. #27458.

Witnesses:

N18°E, 101.64' - N & T in 36" R. Oak (1935 OBT)

N788E, 91.64' - N & T in P.P. (OBT)

N45°W, 84.83' - N & T in 15" J. Pine (OBT)

S50°W, 52.50' - N & T in 13" R. Pine (OBT)

Surveyor's Michigan License No. 27458

ROBISON PROFESSIONAL SURVEYOR

Pessio

APPROVED LAND CORNER P.A. 345 of 1990

Survey, Lapham, 1971

Unrecorded Survey

E-9 to D-9, 2624.8

E-9 to C-9, 5259.5

Survey, Roser, 1994 Unrecorded Survey

E-9 to D-9, 2624.56

E-9 to F-9, 2642.5

Clare County

Signed by

2006 Date

PROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983