

MAR 24 2000

SECTION

For Corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 **Clare County Remonumentation**

199900007863

For Corners in		_	T 3 3 3 0 0 0 0 4 8 P ?
Clare			Filed for Record in CLARE COUNTY MICHIGAN
(County) L	ocated In:	Corner Code#:	CAROL MCALILOY
` ,,		į	On 09-20-1999 At 11:15 am. LAND CORNER 9.00
1. Public Land Survey T.	. 20N R. 5W	I-5	LAND CURNER 9.00 OR Liber 2 Page 27 - 27
	R		OR Liber 2 Page 27 - 27
	R		Instrument Liber Pag
	R	:	199900007863 DR 2 2
3. Miscellaneous S T.	R	<u></u>	
Property in Section S T.	R	<u> </u>	
4. Lot No, Record	ed Plat		Register of Deeds Stamp & File Number
5. Private Claims		,	•
I Mark P. Dahigan in a Galid august, an Italy 1	0 1000 do hamby one	tify that under requirements of	ABCDEFGHIJKLM
I, Mark R. Robison, in a field survey on July 19 P.A. 74, Michigan P.A. of 1970, the corner poi			
conformance with regulations and rules therefor			2 6 5 5 4 7 3 7 2 7 1 7
instructions of the United States Department of			4 7 8 9 10 11 12
decree of a Court of Law and/or that the corner			4 7 8 9 10 11 12
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed			6 18 17 16 15 14 13
below.	, . · · · · · · · · · · · · · · · · · ·		7
			8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all	l in the same tow	n and range, may be	9 + + + + + + + + + + + + + + + + + + +
recorded on this certificate.			10 30 + 29 + 28 + 27 + 26 + 25
			12 21 22 24 25 26
			12-31-32-33-34-35-36-
A. Description of original monume	ent and accessor	ies and/or subsequent	APPROVED LAND CORNER
restoration:	cili and accessor	ies and/or subsequent	P.A. 345 of 1990
1856 Adair			Clare of the Little
Set Post Cor Sec. 10-11-14-15			Chairman fauls. leph
S Pine 6 N61 ½ W 23			Date 9-15-99
S Pine 6 S71 ½ E 24			Date
1971 Lapham, LCRC #12	1097 Lanh	am, (132) 2-975	1994 Roser, DNR Plan R-18-AB
1" Pipe		esses as LCRC #64	Meas. N89-43-39W, 2611.92
East 32.94 Conc. Mon	Same with	esses as LCRC #04	S89-58-24E, 2650.52
N45W 30.77 T.P.	1002 Rose	r, LCRC #693	509-50-2+1, 2050.52
S45W 40.86 12" Oak		od for SW-S11. In 1985	1995 Porter, (132) 03-51
545 W 40.00 12 Oak		ipe in same position. Road	References Corner - No Witnesses
1972 Lapham, LCRC #64		-worked w/new black top &	
S30E 34.7 Twin Oaks		laced w/1/2" re-rod & Mon.	
N60E 50.8 14" Oak		3 20" Oak(clp of 3)	References Corner - No Witnesses
1400E 30.0 14 Oak		0 S.E. Cor Wd. Fr. Bldg.	reterences Corner - No 11 micesses
1976 Gourdie-Fraser, (132) 2-238	West 33' C	_	Plats of Summerfield Park & No. 2
	11 VUL JJ V	V 1/4V+4+	

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: See dossier for detailed report.

S65E 64.3 14" Oak

Fd 1/2" x 18" re-rod in Mon. Box in asphalt pvm't. All witnesses set before 1992 are gone due to road construction. Found all 1992 witnesses

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 36" re-rod with Clare Co. Remon cap marked P.S. #27458 in Mon. Box. Accepted as best available evidence of the accepted position of the corner.

Witnesses:

S50W 40.90 12" Oak

East 32.95 Fd. Mon.

S40W 68.75 Spike in 22" Oak (clp. Of 3) (OBT)

S50W 41.00 S.E. Cor Wd Fr, Bldg (OBT)

West 32,77 Conc. Mon (OBT)

S65E 64.26 Spike in 16" Oak (OBT)

N35E 64.00 Cen. of split rail cor. fence post

Signed by_ Surveyor's Michigan License No. 27458

URVEYORS, JAN.28, 19 REVISED MAY 14, 1 REVISED JAN., 1

Plats of Assessor's Plat of Summerfield

MARK A.

ROBISON

PROFESSIONAL

SURVEYOR

No.

PESSION

No. One.