## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| For corners in  | ruing nequirement (  | DI ACT 74, MICH. P.A. 1970   |   |
|---|--|--|---|
| CLARE   | Located In: Co   | rner Code ##   |   |
| Public Land Survey  | T 20N R 5N<br>T R<br>T R   |  |   |
|   | T R<br>T R   | 10   |   |
| 3. Miscellaneous S  | TR   | Regis  | ter of Deeds Stamp & File Number  |
| 4. Lot No , Recore  | ded Plat   | 10-1-1   | A B C D E F G H I J K L M   |
| I, <u>CARL F. ROSER</u> in a do hereby certify that under requirem in lines 1 and 2 above were in conficurrent manual of survey instruction Management or by a decree of a Cour   | i field survey on  |  | 2 6 5 4 3 2 1 3 3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 7 8 9 10 20 21 22 23 24                                |
| Court of Law; established, re-esta expressed below:   | iblished, monumented, re-monument  | ted, recovered, found as   | 0 30 29 28 27 26 25   |
| •   | s, all in the same town and range  | , may be recorded 1  | 2 31 32 33 34 35 36   |
| -A Description of original monu   | ment and accessories and/or suba<br>A-2  | sequent restoration:   |   |
| B. Description of corner evidence A-2   | THE INTERSEC OF SAND RDS  N-S-E-W BEING 13'± N & 12'± N.  BETW 1983 & 1990 THE IR BY RLS  #18664 MAS DESTROYED.  (APPARENTLY BY PIPELINE  CONST.) THE IR WAS RESTORED  ON 7/27/90 BY ROSER'S SUR  CREW. PER RLS #18664 MITS &  (CONTINUED BELOW)  ce found and/or method applied in  A-2 | n restoring or reestablishing co   | 10 rner:  |
| DEPT LAND SURVEYOR, K DSTLING RECOV'D A 1/2" IR; BY RLS \$18564 JOHN SEDGMAN, (WORKED FOR PAUL LAPHAM ASSOC FOR SOME TIME -SEE KJO FIELD NOTES PG 23. DATED 3-23-76), FOR THE E 1/4 COR OF S-1, T2ON-R6W. IN 1983 ROSER'S SUR CREW RECOV'D SAME IR, BY RLS \$18644, DURING AN ON-BOING INTERNITIENT, RETRACEMENT SUR IN T20 & 21M-R5M; (CONT. IN 'A') | (CONTINUED FROM "A" ABOVE.) RECORD PER 1983 (ROSER CREW) TRAYERSE: THE INTERSEC OF SAND  | FD M. SCHAAF 2" PIPE FOR S 1/<br>COR SEC 6. FD 3 M. SCHAAF   | 4 ESTABLISHED SN COR OF FRL N<br>1/2 OF FRL SN 1/4 OF SEC 6 PER<br>STANDARD BLM INSTRUCTIONS.                     |
| C. Description of monument for  | corner and accessories established   | ed to perpetuate locating the p  | osition of the corner:  |
| A-2<br>SET 1" X 35" GALV PIPE W/X-ARM<br>ON BOTTOM & SET PLASTIC RLS<br>CAP IN TOP OF 1" PIPE.  | A-2  | B-3<br>DROVE 1"X 6" GALV PIPE W/ALUM<br>DNR CAP IN FD RUSTY 2" PIPE &<br>SET CED POST.                       | 10<br>DROVE 5/8" X 34" REROD W/RLS<br>CAP.<br>15" R.PINE N30°W 72.0'  |
| 9" R.PINE N55"N 61.96"<br>47" B.GAK N20"E 39.00"<br>7" R.PINE S50"E 27.71"  |  | 10" MAPLE N25°N 6.9' 10" R. QAK S70°E 20.32' 7" MAPLE S35°E 10.0'  | SET CED POST W/   |
| #8" R.PINE S75"N 47.97" SET CED POST N/ LOC TAG. EAST 16.5" #=RLS #18664 (LAPHAN ASSOC)   | ) 4115 C-22-92   | 14" OAK S10°N 24.51"<br>+24" Y PINE STP N45°N 39.6"<br>+26" Y PINE STP N68°E 41.6"<br>+= MARCUS SCHAFF WITS. | LOC TAG. EAST 16.5'   |
| Signed by   | oser 5-22-92<br>12028  | Date   | F. ROSER  Y SICHIGAN SMAC TORAND OF AND STRVEYORS, JAN. 28, 1971  SURVEYOR  NO.  REVISED MAY 14, 1975  NO.  12028 |
|   |  | •  | AND SURVIVE   |