

(47)

3-30-71

WEST 1/4 COR.
SEC. 19

INTERSECTION OF
DRUMHELLER AND CHANDLER

GOT PULL-DIG LATER

1-15-71 - FOUND R.R. SPIKE JUST
BELOW SURFACE OF BIT.

IN CENTER OF CHANDLER AND
DRUMHELLER. REMOVED R.R. SPIKE,
REPLACED w/ 1/2" COPPERWELD ROD.

1-7-71 - DUG HOLE - REMOVED COPPERWELD ROD.

FOUND 5/8" REINFORCING ROD

3' BELOW SURFACE OF BIT

ROAD IN E OF ROAD. SET 4"

TILE AROUND ROD. RAISED

ROD w/ 3/4" PIPE, SET MON. BOX

N. 35° W. - 80.91' - 16" MAPLE

S. 45° W. - 44.78' - T. POLE

S. 50° E - 60.29' - GUY POLE

N. 55° E - 64.75' - PLAT MON. - BEHIND POLE

