



(49)

5.30-71

S.W. COR - SEC. 19
COMMON TO SECS 30,

INTERSECTION OF
CHANDLER AND STOLL

FD - R.R. SPIKE - FLUSH W/ BIT
WEST OF EXISTING CENTER OF ROAD
R.R. SPIKE BENT - REPLACED
W/ BOAT SPIKE

JOG NORTH - 18.31
~~18.28~~ 1/2" IRON PIN
S.E. COR. SEC 24 - DEWITT
TWP.

S. 65° W. - 49.22' - P. POLE
~~49.25~~
N. 35° W. - 57.13' - 17" OAK
~~57.00~~
N. 50° E. - 87.56' - P. POLE
~~87.54~~

5-7-71 - REMOVED BOAT SPIKE -
REPLACED W/ 1/2" REINFORCING
ROD - SET MON. BOX

A-9

TSN R/LW
MDSH NOTES

22
1.62
11.4
14.4
14.84

245
2070
2070
2171