SURVEY & REMONUMENTATION

FEB 0 2 1998

REMONUMENTATION **DEWITT TOWNSHIP**

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIDER ONLY PART 199

RECOMBID

For corners in			
Clinton (County)	Located in:	Corner Code #	Oct 17 9 14 A1 29
1. Public Land Survey	T_5N_ R_2W TR	K-1	REGISTER A LEGISTICAL CONTROL OF THE MICH.
2. Property Controlling In Section	TR ST_R ST_R_		
Miscellaneous Property in Sec.	STR STR		Register of Deeds Stamp & File Number
4. Lot No. 5. Private Claims	, Recorded Plat		ABCDEFS

5

8

7

a

9

10

12

I, Mark L. VanRaemdonck, in a filed survey on August 21, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1. Original Lucius Lyons 1/6/1827 Mon: Wood Post Access: W. Oak 30 S75°E 65 1/2 DO 14 S63°W 88

S25°E

- 2. Kay Don Fluke L.C.R.C. L. 2, P. 416 10/6/81 Mon: Found 1/2" Bar & Cap #18989 Access: Due East 15.18 1/2" Bar & Cap in Mon. Box Due East 49.06 Conc. Monument \$40°W 41.25 Tag in E. side of 18" Oak
- 3. Richard Steadman, Cert. survey L. 4, P. 747 12/16/91 Mon: 1/2" Iron Rod

Access: Conc. monument West 49,06" 18" Oak S40°W 49.06' 42" Oak \$25°E 41.25 1/2" Iron rod (Olive Twp Cor.) East 15.18

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

60.55 R. R. spike in W. side 42" Oak

Found 1/2" rerod & cap as referenced in No. 2 and 3 above accepted this position as the location of the original corner based on the best available evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner

Removed 1/2" Rerod & Cap and replaced it with a standard Clinton County Remonumentation Monument. The monument is witnessed by the following

MARK L

N70W 27.92 \$30W

Set Nail & Tag #24622 in N. face 12" Oak

\$30W 40.41 Set Nail & Tag #24622 In N. face 24" Oak \$89°41'17"E 15.29' STD Clinton County Mon at K-13, T6N-R2W

North 148.4 Centerline asphalt pavement Round Lake Road

N89°41'17"W 2624.71 STD Clinton County Monument at J-13, T6N-R2W GTATE OF MICHIGA Surveyor's Michigan License No. 24622 CEN

VANRAEMDONCK PROFESSIONAL No. 24622 SATISTICATION OF THE STATE OF THE

CLINTON COUNTEREST CHOUP DATED.