REMONUMENTATION

DEC 07 1994

LAND CORNER RECORDATION CERTIFICATE

For	corners OMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

Clinton	Located In:	Corner Code =##	
(County) 1. Public Land Survey	T <u>5N</u> R <u>2W</u> T R T R T R	M-9(M-13)	MAR 15 3 37 PM '94 REGISTER OF DEEDS CLINTON COUNTY, MICH.
 Property Controlling in Section Miscellaneous 	S T R		LIBER 4, PAGE 14
Property in Sec.	S R		Register of Deeds Stamp & File Number
	, Recorded Plat		2 6 5 4 3 2 3 4 7 8 9 10 11 12
do hereby certify that under in lines 1 and 2 above were current manual of survey in Management or by a decree above were in conformance Court of Law; established expressed below:	P. Sh a field survey on Oc requirements of P.A. 74, Michigan P.A. e in conformance with regulations as structions of the United States Depa of a Court of Law and/or that the corn with the rules of the Michigan Board , re-established, monumented, re-	of 1970, the corner points mention and rules therefore as required in rtment of the Interior, Bureau of Li er points mentioned in lines 3, 4 ar of Land Surveyors or by a Decree monumented, recovered, found	ned the 6 18 17 16 15 14 13 and 7 and 5 8 19 20 21 22 23 24 of a as 10 30 29 28 27 26 25
NOTE: Not more than 4 on this certificat	l corners, all in the same town a te.	11	

- A. Description of original monument and accessories and/or subsequent restoration:
 - M-9 Original survey by Harvey Parke in 1827, recorded in Liber 1, page 169,-Found 1/2" iron with tile cylinder around at 2 ft. below road surface -%" iron in monument box.
 - M-13 Original survey by Harvey Parke in 1827, Recorded in Liber 2, page 362 on 2-24-80. RR spike established by Marv Fouty, P.S. and recorded in Liber 3, page 34, Ingham County records, Survey of Section 31, T5N, R1W agrees with existing point.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Dewitt Township

- M-9 Found 1 rod in monument box Removed 1 rod and placed Standard Clinton County Monument in monument box.
- M-13 Found RR spike as recorded Accepted RR spike as correct position of corner - Set Standard Clinton County Monument in monument box.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(Standard Clinton County Monument

Face end post chain link fence -N30°W- 46.93'

N & T S. side 8"x 8" sign post -\$70°E- 37.17'

M-13 (Standard Clinton County Monument in monument box)

Bath Twp. corner -South- 18.75' MSHD tag SE side power pole -N70°E- 78.00' MSHD tag NW side power & tel pole -S55°W- 59.57'

in monument box)

Center pavement -West- 4.6' N & T S. side guard rail post -S70°E- 13.55' N & T N. side guard rail post -N62°E- 15.45'

N & T N. side 22" Cottonwood -N80°W- 52.55'

N & T SE side power pole -S27°W- 68.01'

**Standard Clinton County Monument is a 2" steel tube, 30" long with a 3½" breakaway magnet ochase

stamped brass cape lieus frem Date November 24,

Signed by _ 13039

SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. The Ison

Surveyor's Michigan License No.