JAN 1 7 1996

## REMONUMENTATION SECTION 2, OLIVE TOWNSHIP

## LAND CORNER RECORDATION CERTIFICATE

MOISSIMM

4. Lot No.

5. Private Claims \_

as expressed below:


1 1

E٥	COMMUNISON r corners in	Filing Requirem	Filing Requirement of Act 74, Mich. P.A. 1970	
Clinton (County)		Located In:	Corner Code #	RECORDED
1.	Public Land Survey	т <u>бN</u> н <u>2W</u>	J-3	SEP 27 9 14 AM '95
		T R T R T R		RECORDED CONTROL OF COLOR
2.	Property Controlling in Section	S T R S T R		Carolo William 1996 LIBER 4, PAGE 74
3.	Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number

August 1 Arden S. Pierson P.S. in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

\_, Recorded Plat\_



- A. Description of original monument and accessories and/or subsequent restoration:
  - Original survey by Hervey Parke in 1827. Set 4 Sec. Post on True Line, W. Oak 20" - S79°E 23 Links; W. Oak 24" - N84°W - 29 Links.
  - County Survey Notes by Charles Hollister, December 1880 Post 3" Yellow Oak S88°E 65½ Links, 8" B. Oak N17½°E 156½ Links. 2.
- LCRC Liber 2, Page 331 by Russell Roon, 9-17-80 Found hole from which post had been removed; 16" Hickory -3. NO5°E -3.44'; 16" Hickory -N25°W -18.32'; 14" Beech -N70°W -37.58'; 17 Maple -N80°E -5.05'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Replaced corner monument from MDOT coordinate geometry traversed perimeter of Section 2, tie to SE corner of Section 2 as shown on the construction plans is defective.

The corner position is accepted as a careful and faithful perpetuation of the original corner.

Set Standard Clinton County Monument and carsonite marker.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 1/4 Corner, Section 2 \*Standard Clinton County Monument Nail & tag #13039 in W. side Power Pole - N12°W - 158.46 West end culvert - N87°E - 98.51' Nail & tag #13039 in N. side 3" Ash - S65°E - 133.18'

I distant County Monument is a 2k" dia steel tube

	*Standard Clinton Coun 30" long with a stampe	ed brass cap and	a 23 ula. a breakawa	y magnetic l	oase.
Signed by_	Chon S. Pieur	<b>-</b>	Date	eptARDEM.6.9,	1 <i>9</i> 05
Surveyor's N	Aichigan License No. 13039		FORM APPROVED BY MICE	GAN STACTES SIONAL SSIONAL SSI	AL SUPJEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1903
		APPROVED BY CLINTON COUNTY PEER GRO DATED 899185		13039	