SURVEY & REMONUMENTATION

FEB 0 2 1998

REMONUMENTATION **SECTIONS 33 & 34, RILEY TOWNSHIP**

SECTION

LAND CORNER RECORDATION CERTIFICATE

	Filing Requirem	ient of Act 74, Mich. P.A. 1	970	
or corners in	•		LIDER OOI	PAGE 237
CLINTON	Located In:	Corner Code #		
(County)	ounty)		RECORDED	
, Public Land Survey	T R		Oct 17	9 20 AH '97
. Property Controlling			AFRICTE	D AF BEERA
in Section	S R			inion.
3. Miscellaneous Property in Sec.	S T H S T R		<i>ಟೌಸ್ಕ್ಟ್ನ್</i> Register of Deeds \$	्रिकारीतः tamp & File Number
7 Toporty III 000.	<u> </u>			
Liot No Re	corded Plat			
				֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓
			2 6 5 4	
Roger P. Mahoney in	n a field survey on July 24	, 19 97 do hereby state	4 - 7 - 8 - 9	10-1112
nd 2 above were in conform	A. 74, Michigan P.A. of 1970, the co nance with regulations and rules then	efore as required in the current	5	
nanual of survey instructions Associated or by a decree of	of the United States Department of a Court of Law and for that the corn	of the Interior, Bureau of Lander points mentioned in lines 3, 4	6 -18 -17 -16 -	15 14 13
nd 5 above were in conforma	ance with the rules of the Michigan E	Board of Land Surveyors or by a	7	
Decree of a Court of Law; esta below:	ablished, re-established, monumented	, recovered, round as expressed	8 19 20 21	222324
IOTE: Not more than 2 com	ners, all in the same town and range, i	may he recorded	9	 - - - - -
IOTE: Not more than 2 com on this certificate.	icis, all in the same town and range,	illay be recorded	10 -30 -29 -28-	- 27 - 26 - 25
			11	
			12 -31 -32 -33	343536
A. Description of original r	monument and accessories and/or	r subsequent restoration:	13	
	Corner Section 33 and Southwest		214/	
		Comer Section 54, 1.0MR.S	, v v .	
Post set by Deputy Beech 20", N.61°E Elm 18", N.44°W.				
(Over)				
. Description of corner e	evidence found and/or method app	olied in restoring or reestablish	ning corner:	
G-13 - Southeast C	Corner Section 33 and Southwest	Corner Section 34, T.6NR.3	BW.	
Found Standard Cli 34976. Also found	inton County Monument being 2 d various witnesses from certifica	1/2" diameter steel tube, 30" te of surveys and L.C.R.C. red	long with a stamped bras corded in L. 1, P. 339.	s cap, set by P.S.#
Accepted the found	d monument as the best available	evidence of the position of th	ne original corner.	
C. Description of monume	ant for corner and accessories esta	ablished to perpetuate locating	g the position of the corne	er:
G-13 - Southeast C	Corner Section 33 and Southwest	Corner Section 34, T.6NR.3	3W.	OF MICHIG
	county Monument being 2 1/2" dia ass cap, restamped # 41105	ameter steel tube, 30" long		ROGER P. MAHONEY
S.45°W., 55.15' N.75°W., 118.86' N.65°E., 72.23'N	N&T, # 12034, SW, face 20" Tw N&T, # 12034, NW, face utility p N&T, # 12034, S. face 24" Ma I&T #, 12034, SE face utility pole numentation corner, G - 1, T.5N.	oole ple 3	Loensel	OFESSIONAL OF
Q.	DM.L		Aug m	-20 1007
Signed by Note 1	- Manoney		Date <u>conjult</u>	, w, 177/
Surveyor's Michigan Licens	e No. 41105 /		. •	

LIBER 004 PAGE 238

Post on Town Line by County Surveyor C. E. Hollister, 1876, Field Book 7, P. 60; Willow 12", R.1 1/2°W., 135 links
B. Walnut 8", N.57°W., 157 1/2 links

County Surveyer C. E. Hollister, Nov. 20, 1879, Found stone set and one witness to ______ Watertown corner, 43 links East of this corner; Willow 12", S.1 1/2° W., 135 links

B. Walnut 8", N. 7 1/2° W., 157 1/2 links

Clinton County Roc 1 Commission Alignment Notes, 1920+/-, Vol. 3, P. 16, 1" iron pipe, 6" down; 10" Walnut, S.17°- 20' W., 31.2' 1 " iron pipe, N.78°- 30' E., 64.1' 1" iron pipe, S. 58°-(-E., 79.3'

L.C.R.C. by F. White, # 12034, May 1972, Recd. L.1, P. 339, found R.R. spike; N.55°10'W., 35.05'-Ai thor Pole S.43°40'W., 55.33'-Pol or Pole N.58°30'E., 72.36'-Anch or Pole

L.C.R.C. by F. White, # 120、1, July 1972, Recd. L. 1, P. 389, found R.R. spike; N.55°10'W., 35.05'-Anchor ele S.43°40'W., 55.33'-Power Pc. N.58°30'E., 72.36'-Anchor Pok

Certificate of Survey by F. White, 3: 12034, July 1972, Recd. L.1, P. 153, R.R. spike in centerline of Cutler Road and Francis Road extended from north; S.43°40'W., 55.33'-Power Pole N.58°30'E., 72.36'-Anchor Pole

Certificate of Survey by R. Helsel # 1899 Oct. 1974, Recd. L. 1, P. 523, refers to comer Recd. L.1, P. 389

Certificate of Survey by J. Stephens, # 1605 3, May 1979, Recd. L. 2, P. 170, R.R. spike with witnesses of: N.55°10'W., 35.05'--Tag in Anchor Pole S.43°40'W., 55.33'--Tag in Power Pole N.58°30'E., 72.36'--Tag in Anchor Pole Recorded in L.1, P. 389

Certificate of Survey by M. VanRaemdonck, # 2462. April 1983, Recd. L.2, P.551, found R.R. spike; S.45°W., 55.30'--C.P. Co. Tag in Utility Pole N.10°W., 30.20'--N. End 24" C.M.P. N.75°E., 72.40'--C.P. Co.

Certificate of Survey by M. VanRaemdonck, June 1991, 1 ccd. L. 4, P. 287, found R.R. spike; S.45°W., (no distance given), C.P. Co, Tag in N. Face S.50°W., 55.30'--Utility Pole N.60°W., 34.25'--Top center telephone cable box S.65°W., 81.36'--Center N. Face 6" White Birch East, 17.90'--Phys. centerline asphalt surface

Certificate of Survey by R. Mahoney, #41105, Feb. 1997, found Clinton County Remon Tablet; N.45°W., 34.32'--N&T, # 12034, SW Face 20" Twin Ash S.45°W., 55.15'--N&T, # 12034, NW Face Utility Pole N.75°W., 118.94'--N&T, # 12034, S. Face 24" Maple N.65°E., 72.30'--, N&T, # 12034, SE face Utility Pole