

Surveyor's Michigan License No. ____13039

NW CORNER OF SECTION 6, RILEY TWP.

LAND CORNER RECORDATION CERTIFICATE

For corners in Clinton		Filing Requirement of Act 74, Mich. P.A		P.A. 1970	1970 PEGORDED			
	(County)	Located In:	Corner Code ##	T.TRER	4, PAG	E 54		
1.	Public Land Survey	76N R3W	A-1	<u> </u>	4, 1110		12 o1 PH '9 4	
•		T Led R 4W TR	M-1			CLINTO	TES DA - ELOS 1700 - BTY, MICH. Co - Ocksely.	
2.	Property Controlling in Section	T R S T R S T R				ccar.	uk — suurin mungga W	
3.	Miscellaneous Property in Sec.	S T R S T R		Reg	Register of Deeds Stamp & File Number			
		Recorded Plat			∆ B	CDEF	G H I J K L M	
5.	Private Claims				2	Į Į		
	•	•			3			
in I cur Ma abo Cor exp	thereby certify that under re- tines 1 and 2 above were trent manual of survey inst nagement or by a decree of ove were in conformance wourt of Law; established, pressed below: OTE: Not more than 4	S, in a field survey onMar- equirements of P.A. 74, Michigan P.A. in conformance with regulations an irructions of the United States Depart if a Court of Law and/or that the corne with the rules of the Michigan Board of re-established, monumented, re- corners, all in the same town ar	of 1970, the corner points mend rules therefore as required timent of the Interior, Bureau or points mentioned in lines 3, of Land Surveyors or by a Decimonumented, recovered, for	ntioned I in the of Land 4 and 5 ree of a und as	5 6 — 18— 7 8 — 19— 9 10 — 30— 11		22 23 24 27 26 25	
	on this certificate	3 .			13	32 33	34 -35 - 36	
	Recorde large f to 1 ft it." Wi Wood 26" 22" Tele	al survey by Harvey ed in Liber 2, page flat-topped stone 6" below surface and th Witnesses: lanchor post -S88°E Hackberry -N76°W- 1 Apple -N18°E- 78.02 ephone pole -S08°E-	232, by Richard below road sur deposited 5 rase 20.29' 113.86' 2' 155.54'	stead face. I	Lower€ spik€	ed stone es arour A CLINTON (•	
В.	Description of corner	evidence found and/or method		stablishing	corner:			
,			Riley Township					
	A-1 - Found 1/2" rod - 12" long, dug down and found stone with 5 RR spikes around it - Removed 12" long rod and drove 1/2" rod 24" long on South side and bent top of rod to point of stone. And accepted as a careful and faithful perpetuation of the position of the original corner. Removed 1/2" rod and RR spikes and Set Standard Clinton County Monument 8" below road surface. Placed stone on the North side of monument and deposited rod and RR spikes around the monument below the brass cap. (Thise Of Michigan Corner is common to the following Townships, Westphalia, halles." Arden S. Pierson							
C.	Description of monum	nent for corner and accessories	established to perpetuate	locating the	e positio	n of the com	ier:	
		A-1 (NW corner	r Section 6)		·		13039	
	PK nai Nail 8 North NW com	il & tag in S. side & tag #11370 N. side edge Stop sign pos rner telephone pede	32" Hackberry - e leaning wood t t -S72°W- 34.16° stal -N45°E- 46	-N75°W- fence p '	114. ost -	15' S86°E- :	20.42	
	with a stamp	inton County Monume oed brass cap and b	nt is a 2½" dia reakaway magneti	. steel ic base	tube.	30" 101	ng	
Sic		a S. Pum		NOVEMBE	ER 1,	1994		