



(SECTION "A" CONTINUED)

M-03 Standard Sec. Cor. of 1 & 12, T7N-R1W

John D. Matonich Jr., #31598, on an L.C.R.C. dated 29 October and recorded in Liber 2 at page 651 and a survey dated 29 October 1987 and recorded in Liber 3 at page 227 found a re-rod in a monument box 2.7' West of pavement centerline. He marked the following references: N 45 E 22.62' bar & #20709 cap, S 45 E 22.30' bar & #20709 cap, S 45 W 18.89' bar & #20709 cap, N 45 W 18.57' bar & #20709 cap.

Dwight R. Schofield, P.S. #34976, on an L.C.R.C. dated 17 May 1995 and recorded in Liber 3 at page 5, found a 1/2" rebar in a monument box and noted the following references: N 50 W 92.82' SE Corner No. #1405, N 20 W 136.17' Service Pole, N 45 W 47.62' 24" Maple, N 20 E 187.40' Service Pole.