SURVEY & PENONUMENTATION

FEB 0 2 1998

REMONUMENTATION

SECTION

SECTION 25. DUPLAIN TOWNSHIP

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 004 PAGE 216

For corners in				ULPAKAED						
Clinton (County)	Located In:	Corner Code #					j.,			
1. Public Land Survey	T <u>8N</u> R 1W T R T R	M-10		6	REGIS	JER 6	18 M	(8		
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		Register of Deeds Stamp & File Number							
4. Lot No, F	Recorded Plat		₁ /	A B	C D	E F	в н	I J K	L M	
5. Private Claims			2	6	5	4	3	2	1	
I, Wendy A. Papineau , in a field survey on June 1997 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			3 4 5	7	8	9	10	17	12	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land				18	17	16	15	14	13	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded			7 8	19	20	21	22	23	24	
			9 10 11	30	29	28	27	26	25 €	
on this certificat	•	s and/or subsequent restorations	12 13	31	32	33	34	35	36	
, -	nal monument and accessorie 1/4 Corner Section 25, T81	s and/or subsequent restoration: <u>v-r1w</u>	13 •							

Wood post placed by Robert Clark Jr., D.S. Jan. 26, 1831 N 53 W 3 lks (1.98') 8" Beech S 33 W 41 lks (27.06') 12" Lynn

Clinton County Survey Records (Source & date unknown) "Set stone, two bricks on NE side stone" S 87 W 1.99 lks (1.31') 8" Hickory

Unrecorded survey by James Porter (E.D.I.) Oct. 1987, Job 644-F (rev). Ran the East line of Sections 13,24,25, and 36 in searching for reliable positions for government corners along this line.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-10 Standard East 1/4 Corner Section 25, T8N-R1W

Found no evidence of hickory. Calculated a position on the Michigan Meridian at a midpoint between Standard Section Corners of Section 25. Excavated a 2.0' dia. hole 3.5' deep, found no evidence of the record stone and bricks. Also, there is no evidence of occupation.

There appears to be no conflicting evidence and this position is accepted as a careful and faithful determination of the position of the original corner.

Approved by the joint Clinton/Shiawassee County Remonumentation Peer Review Group August 13,1997.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard East 1/4 Corner Section 25, T8N-R1W M-10

Placed a Clinton County Monument, 2"x30" steel pipe, 3 1/4" brass cap, stamped M-10 T8N-R1W PS 41919, and plastic base with magnet in a monument box.

N45E 25.09' Set 1/2" rod w/flagging N50W 23.79' Set 1/2" rod w/flagging S45E 23.26' Set 1/2" rod w/flagging \$50W 18.10' Set 1/2" rod W/flagging



APPROVED BY CLINTON COUNTY PEER GROUP 8/13/97

DATED _

Surveyor's Michigan License No.

Date

ICHIGAN STATE ROARD OF LAND SURVEYORS, JAN. 28, 1971