SURVEY & REMONUMENTATION

MAR 2 9 2000

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

Filing Requirement of Act 74, Mich. P.A. 1970						
For come			cated In:	Corner Code #	ı	STATE OF HICHIGAN CRAWFORD COUNTY
	(County)					RECORDED
1. Public	Land Survey	T <u>25</u> N	_R _R _2W _R _R	B-13		17 AUG 99 12:29 P.M. SANDRA MOORE REDISTER OF DEEDS
2. Proper in Sect	ty Controlling	ST ST	R			•
3. Miscell		ST ST			Re	gister of Deeds Stamp & File Number
4. Lot No, Recorded Plat, A B C D E F G H I J K L M						
	e Claims	BER	4 PAG	E 05	2 is of P.A.	2 - 6 - 5 - 4 - 3 - 2 - 1 - 3 - 4 - 7 - 8 - 9 - 10 - 11 - 12 - 12
74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered,						
found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recor					rded	10 30 29 28 27 26 25
	on this certificate.				1 1 1 1 1 1 1 1 1 1 1 1	
A. Description of original monument and accessories and/or subsequent restoration:						
•	G.L.O - 1838 John Brink D.S. Mon Post 4" White Pine N47 1/2° 6" White Pine N51 1/2° Plat of Indian Glens Uni	Lil M W 19 links. V E 26 links	eorge D. Henning #2241 ber 328, Page 440; Mar on: 3/4" pipe Vit. 12" Elm N84°E 48.6 5" Elm S54°W 33.6	ch 1977 Mon: Wit: 1 3' N	Bolt in paven Nail in top 6" ; Nail in top 6" ; Nail in top 6" ;	P.S. #31600 (unrecorded survey 1995) nent box 3'± West of centerline. x 8" guard rail post \$50°W 21.04' x 8" guard rail post \$30°E 35.49" x 8" guard rail post \$75°E 23.69' 14" Poplar N47°W 41.53'
May 27, 1970 by C.E. Ostling, #12026 Chepp's Manor Aug 25, 1972 N. Parker #16939 Mon - unknown Wit: Concrete Mon N89°56″W 33.00 Wit: none given B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Cabin Spike in Monument box raising a 3/4" pinch pipe 1.4' below the surface and 31'± North of the North bank of Beaver Creek. Nail in top 6" x 8" guard rail post S50°W 21.04' Nail in top 6" x 8" guard rail post S30°E 35.49" Nail in top 6" x 8" guard rail post N75°E 23.69' Nail NE side 14" Poplar N47°W 41.53' Accepted %" pinch pipe as the best available evidence of the position of the Original Corner. Replaced pipe with Standard Roscommon County monument.						
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Mon: Standard Roscommon County corner in existing monument box. Wit: Found spike in NE face 12" Poplar N47°W 41.53' Found Roscommon County reference nail & tag in utility pole N82°W 30.75' Found Spike in top of end guard rail post N75°E 23.69' Set nail & tag in 6" Balsam N31°E 106.17' Set nail & tag in 8" Balsam N61°E 43.31' DATE June 7, 1999						
	~	_	MINIMUM CO.	IN E. RS	9	NAME - Myw MEM Marvin E. Myers, P.S. County Surveyor
Signed by	y Michigan License	- My No. 31600	MARVIN MYER		Date ,	June 9, 1999
·	-		MARVIN MYER PROFESSION NO. 31600	ONAL SURVINIA	OVED BY MICHIG	IAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1 REVISED MAY 14, 1 REVISED JAN., 1 REVISED OCT., 1