MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

			COUNTY
DESCRIPTION	OF	CORNER	Section Corner serves in Sections 18,19,19,24
DESCRIPTION	OF	CORNER	MONUMENT 24 Pape with 49 Bress_eap
WITTNESSES	то	CORNER	_ 30% Red Ock = 8-45 W 34-54xks
		•	79_Red_Galt = N .50 R = 97 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by the Percetty Division survey eres, while making a particl reservey of this area, One original B.T. still in place, in poor condition. Corner had been proviously located by S. B. Hemning, R.L.S., in 1997.

Souther was placed and witnessed July 15, 1954.

SURVEYORS SEAL

SIGNED DATE 9/26/54
REGISTERED LAND SURVEYOR