## LIBER PAGE 347

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SIME OF	MOHRAR
COUNTY	# GREEN CRO

	. Conners in		
	Crawford	Located In:	Corner Code //
١.	Public Land Survey	T 27NR 1W	F-13 G-7
		<u>I</u> <u>R</u>	
		T R	
		T R ,	
3.	Property Controlling	S T., R .	
	in Section	S T R	
3.	Miscellaneous	S T R	

For corners in

Property in Sec.

FILED FOR RECORD THIS NATE OF STANKE TO YAY 30m/pm, Iri LIBER 2

Register of Deeds

OF MICHIE

ELINED LAND

Register of Deeds Stamp & File Number

ŧ.	Lot No	
Š.	Private Claims	
		· · - • •

S \_\_\_\_\_ R ...

orman C. Caldwell March 90

to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned provided in the n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Aanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Jourt of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 1. Description of original monument and accessories and/or subsequent restoration:
- E = 131Post set by Mullett in 1839. Tamarack 6" N86°E .30 (19.80') Pine 4" N05°W .13 (8.58') Pine
- Post set by Pettibone, July 17, 1852. Y. Pine 24" N15°E .40 (26.40') Y. Pine 20" N52°W .32 (21.12') 3 - 7)
- NORMAN CALP i. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- LaGuire fnd. a post & two Tamarack stumps, 1934. E-13)His distance was 38.95 chains from the SE sec. cor. This area is now in flood waters & inaccessible
- 3-7LaGuire placed pipe & conc. mon. at an existing post & verified by both orig. BTs.

  N. Parker, LS 16939 fnd. mon. Nov. 3, 1976 & rec. in L 2, pg 102.

  K.J. Ostling, LS 10068 fnd. mon. Sep. 19, 1978 & replaced w/DNR mon. S44°W 41.85' 14" Oak S09°E 57.7' 20" R. Pine rec. in L 2, pg 193

Description of monument for corner and accessuries established to perpetuate locating the position of the corner:

			, and promotest the contest,
€-13)	Standard 1/4 cor. Sec. 33, T27N-RlW	(G-7)	Sec. cor. 15,16,21&22, T27N-R1W
	This area is now in flood waters & inaccessible	Fnd. DNR pipe & cap. And is accepted as a careful & faithful perpetuation of the position of the orig. corner. North 1' Carsonite Witness Post S14°E 57.5' 21" R. Pine (R) S40°W 42.2' 17" Oak (R)	
			S70°W 93.2' 10" R. Pine S68°E 92.4' 9" Cedar East 10.9' anchor post

April 26, 1990

igned by urveyor's Michigan License No. \_\_\_\_\_\_12018

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971