REMONUMENTATION

APR 2 7 1995 CRAWFORD COUNTY COMMISSION PEER GROUP APPROVAL LIBER PAGE Date Dec 22, 1994 noin E. Myon CRAWFORD COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Marvin E. Myers, P.S. Filing Requirement of Act 74, Mich. P.A. 1970 STATE OF MICHIGAN For corners in ALSO ACT 345, PA 1990 CRAWFORD COUNTY CRAWFORD Located In: Corner Code ## RECORDED 10 FEB 95 8:40 A.M. **Public Land Survey** T 28N R 2W ___ R __ ELIZABETH H. WIELAND REGISTER OF DEEDS **Property Controlling** __ T ____ R __ _ T __ __ R __ in Section Miscellaneous __ T ...__ R .__ Register of Deeds Stamp & File Number Property in Sec. __ , Recorded Plat __ 4. Lot No. Private Claims i, Wayne E. Boss , in a field survey on December 8 . 19 . 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: G.L.O. James Mullet 1839 Set post cor. 11/2" Pipe set by R. Ostling. Notes not found. N. Parker Sections 24 & 25. recorded cor. L.2 pg. 122. 1. y Pine 6" S29°W, 9 lks. 1. B.T. 4" Maple S.W. - 25.8' (S47°W, Marlatt) 2. Pine 6" N89°W, 7 lks. 2. B.T. 4" Oak N.W. - 21.6' (N20°W, Marlatt) Additional Marlatt Wit. (1994) Mullet Dist. from M-11 80.00'. Surveys: W. Warner D.S. 1858 Dist. 79.86'. 3. North 6" Maple 17.4'. Parker L. 181, pg. 552. L. 184, pg. 264. L. 170, pg. 352. 4. N85°E, 5" Maple 28.0'. Marlatt L. 381, pg. 94. L. 350, pg. 470. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Fd. 11/2" Pipe in N.S. Fence. 1. Fd. Blz. 5" Maple N85°E, 28.0'. Fd. 8" Maple \$47°W, 25.8'.
 Fd. 9" Oak N20°W, 21.6'. 4. Fd. Blz. 5" Maple North 17.4'. G.L.O. Mullet 1839 - 2640 to M-8 W. Warner D.S. 1858 - 2623.5'. 2605.70' (N. Parker) Meas. 2604.62' G.L.O. Mullet 1839 - 2640 to M-10 Warner 1858 - 2628.12' Meas. 2641.73'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-9 Set Crawford Co. Mon. at exact location of 11/2" Pipe. Spk. 5" Maple N85°E, 28.33'.
 Spk. 8" Maple S42°W, 25.97'.
 Spk. 9" Oak N28°W, 21.72'.
 Spk. 5" Maple N05°W, 17.58'.

4. Spk. 5" Maple N05"W, 17.56".

This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner. Jun T WAYNE E. BOSS PROFESSIONAL 1985/VEYOR No. Date _ Signed by Wayne E. Boxs PS

Surveyor's Michigan License No. 20703

ROOF KAND SURVEYORS, JAN. 28, 1971 MARCHAN CONTRACTOR OF THE STANKE REVISED MAY 14, 1975 REVISED JAN., 1983