SURVEY & REMONUMENTATION

ADD	Λ	7	1992

APR 0 7 1998						
SURVEY &	LAND CORNER	RECORDATION CERTIFIC				
For corners in SECTION	Filing Require	ment of Act 74, Mich. P.A. 1		מאסרי.	0 16	,
Crawford		LIBER	3	PAGE	ICHTGAN 4	5
(County)	Located In: Co	orner Code #		CRAWFORD (
4 Dukka kanad Awara	~70NI~4XI	T12X		RECOR)ED	
1. Public Land Survey	T <u>28N</u> R <u>4W</u> T <u>27N</u> R <u>4W</u>	1-13		5 JAN 98 10)*77 A H	
	TR			ม JMR 70 IV	/+O/ Haffa	
O Deamant Cantentline	TR		_	Sandra i		
Property Controlling in Section	S T R			REGISTER (of deeds	
3. Miscellaneous	S TR			·		
Property in Sec.	S R		/ 	lates of Dands	. Ctaur 0 F	Zia Nicos
1			Heg	ister of Deeds	s Stamp & r	ile Num
4. Lot No, Records	ed Plat					
5. Private Claims			A B	CDEF	G H I	JK
			2 6-			- 2
	ru 10 13	97	3			
I. James L. Schwandt , in requirements of P.A. 74, Michigan F	4 - 7-	 	1'0	-1 1		
in conformance with regulations instructions of the United States De	and rules therefore as required	in the current manual of survey	5			
of a Court of Law and for that the co	orner points mentioned in lines 3, 4	and 5 above were in conformance	6 -18	17-16	15-	14-
with the rules of the Michigan Boar re-established, monumented, re-mo			7			+ +-
,	•	,	819	20-21	22	-23
			9			1
			10 30-	29 28	27-	26
			11	32 33	34	35
			12 31-	3233		
A. Description of original monu	ment and accessories and/or	subsequent restoration:	13		•	
1 12 Many D 137						
I-13 T28N-R4W G.L.O. W. Warner, 1856	A. E. Newman, 1903 Sunk T RR Iron 2' Long for Cor	N.F. Parker, 1982 1/2" Bar				
Set Post 18" Hemlock N35°W, 12 Links	G. D. Henning, 1977	8" Poplar S35°E, 98.4′ 8" Maple N29°E, 89.4′				
12" Hemlock N36°E, 11 Links	1/2" Bar	8" Maple N41°W, 68.9'				
A.E. Newman, 1901	10" Poplar \$35°E, 98.4′ 12" Maple N29°E, 89.4′					
10" Tamarack S60°W, 30 Links 11" Cedar S21°E, 13 Links	6" Maple N41 °W, 68.9'					
B. Description of corner evidence f	ound and/or method applied in res	toring or reestablishing corner:				
Fnd. Bent 1/2" Bar	,	CRAWFORD COUN	ITY			
Fnd, Nail 12" Maple N29°E, 89.45' Fnd. Nail 12" Maple N41°W, 69.00' Overgrown & Badly Bent PER GROUP AP						
1110.11ml 12 11mplo 11+1 11,00.00 OT	agrown & Dadiy Den	DATE OCT 16	199	7 1		
		DATE OF TO	<u> </u>	W/		
		DATE OCT 16 Marin E. M	year for	/*		
		Marvin E. Myers,	, P.S.			
		County Survey	or/	-	OF MIC	L .
C. Description of monument for corr	ner and acceptantiae autablished to	nameture locating the position of t	ha cornar	SATE	OF MICHICA	
o. Description of mortaliness for son		beibernare incarriff rise bosition or r	tic Colliel.		AMES L. 🧵	1, 1
Replaced 1/2" bar with C.C.M.				Z {	HWANDT	1 *
C.C.M. is accepted as a careful and faith	ul perpetuation of the position of the o	riginal corner.			FESSIONAL URVEYOR	HO,
Set Spk. PP N65°W, 95.60'					No. 26466	133
Set Spk. PP S70°W, 105.47' Set Spk. 10" Twin Aspen S40°E, 74.55'						J.C.
Fnd. Nail 12" Maple N29°E, 89.45' Fnd. Nail 12" Maple N41°W, 69.00'				70	ESSION	A. C.
1110.110112 Maple 1171 W, 07.00					MARKET .	
	\mathcal{L}	·		•		
a u James	lehan de		17-10	-97		
Signed by	VIM TONON	Date	12-19	p-//		
Surveyor's Mickigan License No	26466	· · · · · · · · · · · · · · · · · · ·				