SUNVEY OF **ENCONUMENTALIS**

NOV 2 1 1997

COMMISSION

STATE OF MICHIGAN COUNTY OF CHARLEVOIX RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

97 APR -4 AM 10: 18

		3 4									
Fo	r corners in				Railano	12	(1)	2.0	2	•	
	CHARLEVOIX	Located In:	Corner Code =##	<u>C</u> ,						_	
	(County)				REGIS	IER (שט אנ	.EDS)		
1.	Public Land Survey	T 33N R 5W T 33N R 6W T R	M-8								
		T R									
2.	Property Controlling	S T R									
	in Section	S T R:									
3.	Miscellaneous	S T R		Register of	Deeds	Stam	p & F	-ite	Num	ıber	
	Property in Sec.	S T R		<u></u>							
4	Lot No F	Recorded Plat		A F	я с в	E F	= G	u		K	
5	Private Claims				<u>, , , , , , , , , , , , , , , , , , , </u>	Τİ	Ť	"	İŤ	Ť	Ť
٠.	1111410 0141110			2 - 6	5-	┿╌┿		· 3	<u> </u>	+	- [-
				3	$\bot \bot \bot$			$oldsymbol{\perp}$	\sqcup		
I, .	TERRY E. BRAND	. in a field survey on	CTOBER, 22 . 19 96			- -	\perp	<u> </u> _		-	-12- -1
do	hereby certify that under re-	quirements of P.A. 74, Michigan P.A	of 1970, the corner points mention	ned 6 1	9 7-	- 1E	; _	 -15—	<u> </u>	•—	-13-
	do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land							_	\sqcup	\perp	\perp
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					}20	21 21	-	 22— 	 -23 	, -	 -24-
	Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:					26		27—			
	•	ornare all in the same town a	and range, may be recorded	11				Ī_			Ĩ
147	NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.										J.
	on this certificate.	•		12 3' 13	1——32— 1	33 		34—	1 35 1	<u> </u>	~36~
A.	Description of original	monument and accéssories an	d/or subsequent restoration:	1,5 =							
	-		& M-8 Section 24, T33N-F	RKW							
184	0, Township Lines by John Muli	ett, Set ½ post. Hemlock 14" N31°W 37	lks.(24.42'), Beech 12" S36°E 42lks.(27.	.72')							
187	7, Co. Surveyor E.K. Robinson (Co. Surveyor's Rec. pg.335), Fd. corner i	oost, Accessories same as GLO.								
190	8, Co. Surveyor E.A. Robinson s	hows cor. on Minutes of Hwy. survey &	Elm shade 3" N66°W, 451/slks. (30.03')								
192 196	2, R. Kent(MDOT), LCRC. Lib.	mise. book pg.85, book 119 pg. 32), Fd. 1 Pg. 135, Set ¾" Iron Pipe at ¼ cor. by East 32.67', Fence Post South 29.19'	& Set New ½ post. New Acc. Elm 14' single proportionate measure to GLO.	" S89°W 1671ks.(1 Elm 4" S70°E 19.4	10.22') 6',						

1970, James Scott RLS #8318, Shows corner on survey. No description or accessorie

1965, Ted Miller RLS #10698, Shows corner on survey as a 1/2" pipe. No accessories given

1978, John E. Ferguson RLS #24595, LCRC. Liber 002, Pg. 83, Fd. T-iron, Utility Pole South 73.3', Elm 5" East 32.6', Elm 3" S62°W 44.63', Poplur 5" N44°E 60.84' 1979, Sherman Chamberlain RLS #25834, Fd. ½" pipe. P.P. South 78.05', 5" Elm East 32.60', 2" Elm S60°W 46.95', P.P. N15°E 138.0', "T" iron S01°16'E 4.75'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Charlevolx Co. Surveyor A-8 1/2 corner common to Section 19, T33N-R5W & M-8 Section 24, T33N-R6W APPROVED

Fd. 34" pipe. Fd. Base of fence post to South 21.23' Fd. "T" iron S04°28'13"E 4.77\$ignature Many C. Femoll Fd. Power Pole South 78.32'; Fd. 7" Poplar stump, N45°E, 57.99' Date: Odt. 24, 1996

Pipe set by Kent was placed by single proportionate measurement without regard to County Surveyor measurements of record. Traverse was run ½ mile North, East, and South. Distance from section corner to section corner (A-7 to A-9) compares well with GLO and County Surveyor. Section line to South and Quarter line to East, as monumented by County Surveyors in 1908, 1928, places corner position 7.96 feet north of 3/4" pipe. Position of corner was reestablished by holding the 1908 & 1928 County Surveyors monuments and setting a Charlevoix County Monument at that location.

C. Description of monument for corner and accessories established to perpetuale locating the position of the corner: A-8 /4 corner common to Section 19, T33N-R5W & M-8 Section 24, T33N-R6W

Set 3" cast iron Charlevoix County Monument at retracement location.

Fd. 34" pipe, S07°24'36"E, 7.96'; Fd. "T" iron, S 06°18'30" E, 12.72'; Fd. 7" Poplar stump, N52°E, 53.58

Fd. base of Fence post, S 04° E, 29.16'; Falls on € road to North. Falls 3.5' North of € to West.

Set nail & tag, 9" Elm, S31°E, 19.03' Set nail & tag, 10" Elm, S08°W, 30.34"

Set nail & tag, Power Pole, S02°E, 86.26' Set nail & tag, 10" Beech, N29°E, 85.53'

Set nail & tag, Power Pole, S52°W, 190.22'

Corner is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by _

33969 1968 003 AAGE 98

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1974 REVISED MAY 14, 1975

REVISED JAN., 1983

TERRY E.

BRAND PROFESSIONAL **SURVEYOR** No

33969

Surveyor's Michigan License No.