
REC		
FOR) [['ORB

MAY 0 5 1997	LAND CORNER RECORDATION CERTIF Filing Requirement of Act 74, Mich. P.A.	RECEIVED FOR RECORD
(County)	ocated in: Corner Code #	96 DEC -6 AMII: 23 Jaannes Spray
Public Land Survey Property Controlling in Section Miscellaneous	T33N R 3W A-9 T R T R T R T R T R T R T R T R T R T	CLERK/REGISTER CHEBOYGAN COUNTY, MICHIGAN Register of Deeds Stamp & File Number
Property in Sec. 4. Lot No, Recorde 5. Private Claims, Recorde 1,	in a field survey on Oct. 2 196 do hereby state that the P.A. of 1970, the corner points mentioned in lines 1 and 2 above we have therefore as required in the current manual of survey instructions and the survey in the survey	A B C D E F G H I J K L 1 2 6 5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		12 31 32



A. Description of original monument and accessories and/or subsequent restoration:

M-9 CORNER COMMON TO SEC 24 & 25 T33N-R4W and SEC 19 & 30 T33N-R3W

GLO: Set post 24" Sugar S09°W 27 lks (17.82') 8" Sugar N54°E 11 lks (7.26') by John Mullett in 1840

5-13-1909

E.A. Robinson survey Shows Sec corner **New Bearing Tree** 36" Hemlock N28 1/4°E 111 lks (73.26')

June 1970 Survey by Charlevoix Abstract & Engineering Found corner 15" Elm N07°E 22.80' Tw. 4" Elm N37°W 18.00' 17" Basswood S38°W 33.10'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/4" pipe with concrete base in center line of 2 track road.

Found old stump N7°E 22.8' Found old stump S55°E 33.10'

GLO to M-8 = 2640°

GLO to M-10 = 2640

C.A.&E. 1970 = 2660.27

Meas

 $= 2660.35^{\circ}$ Meas

= 2643.37'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced pipe with Charlevoix County cast iron monument.

Tw 14" Maple N24°E 43.93' set nail & cap #22431 in NE side

S30°W 31.88' set nail & cap #22431 in West side N08°W 26.95' set nail & cap #22431 in West side 8" Maple 6" Maple

4" Maple

N39°E 22.88' set nail & cap #22341 in SE side

LIBER 010 PAGE 214

Marin's O. Pa



and is accepted as a careful and faithful reestablishment of the position of the original corner	
--	--

Aliu is determined	
	> /m-
Signed by	22/21
Surveyor's Michigan License No	22431
Ontaching teneral	

Date	10-10	.96