MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 37 N.R.'s 24 and 25 W

		COUNTY
DESCRIPTION OF CORNER	Section corners for sections T37N, R25W 12/7 T37N, R24W	
CORNER MONUMENT	l" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND W	/ITMESSED <u>11/4/68, F. J. Bray</u>	
WITNESSES TO CORNER	12" Hemlock (S.6) (NBT) N 15 $^{\circ}$ E, 05 $\frac{1}{2}$ links	
T 3 N -	14" Cedar (S.12) (NBT) S 54° W, 38½ links 13" Hemlock (S.1) (NBT) N 85° W, 15 links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 2 rotted cedar stumps to SE, Hemlock stump bottom. These check well for bearings and distances of original B.T.'s. Stumps in poor condition with no marks visible. Corner checks well with other corners in area.

SURVEYOR'S SEAL

SIGNED PREGISTERED LAND SURVEYOR DATE 11/22/68

Frank J. Bray