

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T.'s 37 & 38 M.R. 24W

	Delta	COUNTY
1/4 corner for sections	T38N, R24W, 31 T37N, R24W, 6	
1" iron pipe with 4" alu	uminum cap	
. 7" Cedar (1/4 S) (NBT) 1	N 88° W, 34 links	
AND		
	1" iron pipe with 4" alm  WITNESSED 11/1/68, F. J. 1  7" Cedar (1/4 S) (NBT) 1  6" Tamarack (1/4 S) (NB	1/4 corner for sections T38N, R24W, 31  1" iron pipe with 4" aluminum cap  WITNESSED 11/1/68, F. J. Bray  7" Cedar (1/4 S) (NBT) N 88° W, 34 links  6" Tamarack (1/4 S) (NBT) North, 34½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from rotted wood post which checks with tamarack stump which M. McNabb witnessed in 1918 according to survey notes in Delta county courthouse. Point of post at end of fence line to east. McNabb stated both B.T.'s were in place in 1918.

SURVEYOR'S SEAL

SIGNED THE 12/4/68 DATE 12/4/68

Frank J. Bray