Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

N.R.

24W

		YTHUO
DESCRIPTION OF CORNER	Section corner for sections $\frac{3/2}{10/11}$	
CORNER MONUMENT	l" iron pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND	WITNESSED 12/9/68, F. J. Bray	
WITHESSES TO CORNER	. 7" Cedar (S.3)(NBT) N 06° W. 88 links	
N la	9" Cedar (S.11)(NBT) S 75° E, 65½ links	
+	1" iron pipe S 85° E, 13-1/4 links	-
CIRCLE CORNER RECLETESED	rotted 28" W.Pine stump (original B.T.) N 34° E, 31 link	s

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

T. 37

This corner was replaced from rotted W.Pine stump which had butted portion of upper face and lower blaze lying at it's base. Cruiser for Sawyer Stoll Company remembers this to be an original B.T. about 20 years ago. Depression in ground where B.T. to SW may have been. W. Pine stump to south checks for distance of line tree.

SURVEYOR'S SEAL

SIGNED Transfer DATE 3/6/69

Frank J. Bray