## SURVEY & REMONUMENTATION

SEP 1 3 1994

For corners in

## COMMISSION

Approved By Delta County Land Survey Remonumentation
Peer Group Under Act 345 Of
A-Ot 1990 On July 13, 1994

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

3, 3

	DELTA	Located In:	Corner Code ##	,		
	(County)	20.44 21.44		Aug 12 1994	_	
1.	Public Land Survey	T <u>38 NR 24 W</u> TR	A-7 k A-8	et 9:00 clock AM in Liber 8	Page 30	
		T R T R		Weller C. Thum 1		
2.	Property Controlling	S		Deita County, Michigan		
3.	in Section Miscellaneous	S T R S T R		Register of Deeds Stamp 8	k File Number	
	Property in Sec.	S T R				
		ecorded Plat		A B C D E F C	HIJKL	
5.	A-7 [	NW COR S19] A-8 [W1/4 COR S19]		2 6 5 4 4	-3-2	
				3 4 7 8 9	_101112	
1, _		in a field survey onuirements of P.A. 74, Michigan P.A. o		tioned   henoit		
in I	ines 1 and 2 above were in	conformance with regulations and ctions of the United States Departn	rules therefore as required	in the 18-17-15-15-15-15-15-15-15-15-15-15-15-15-15-	1/5 1/4 1/3	
Ma	nagement or by a decree of a	Court of Law and/or that the corner h the rules of the Michigan Board of	points mentioned in lines 3, 4	and 5 8 19 20 21	_222324-	
Со		e-established, monumented, re-mo			272625-	
NC		orners, all in the same town and	d range, may be recorded			
	on this certificate.			12 31 32 33	343536-	
A. Description of original monument and accessories and/or subsequent restoration:  A-7 (NW COR S.19) WOOD POST - JAMES H. MULLETTE, D.S 1848 (BIRCH 12"-S33"W-31 LINKS) (HEMLOCK 8"-N21"W-23 LINKS)  GEORGE ADAIR, D.S WOOD POST - 1852 (HEMLOCK 22"-N71"E-23 LINKS) (HEMLOCK 30"-S60"E 27 LINKS)  NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION						
		FOST - JAMES H. MULLETTE,D.S F SUBSEQUENT CORNER RECOVERY OR		14 LINKS) (CEDAR 6"-N63°W-19 LINKS	)	
B.	A-7 [NW COR S.19] FOUND AND IN POOR CONDITIO RD TO THE EAST, THIS EXISTING MONUMENT AS	vidence found and/or method ap IN PLACE, ORIGIN UNKNOWN, A 1-1, N), 2' M/L WEST OF THE C/L OF N- POSITION FITS WELL WITH EXISTIN BEING THE BEST AVAILABLE EVIDEN MONUMENT IS BADLY BENT & IN PO	4' I.P. IN LINE WITH ANC S COUNTY RD & 3' M/L SOU' NG FENCES AT THE 1/16 LINI ICE AS TO THE LOCATION OF	IENT FENCE LINE (DOWN PH OF C/L OF COUNTY ES N & S. ACCEPTED THE POSITION OF THE	M. P. DAVIS ND SURVEYOR	
	WEST & 6' M/L WEST O AT THE 1/16 LINES N	D IN PLACE, ORIGIN UNKNOWN, A 1'F THE C/L OF THE N-S COUNTY ROAD S S. ACCEPTED EXISTING MONUMENT TION OF THE ORIGINAL CORNER, COMMAINTENANCE.	). THIS POSITION FITS WELL AS BEING THE BEST AVAILAD	L WITH EXISTING FENCES BLE EVIDENCE AS TO THE	NO. 16926 STATE	
C.	A-7 REPLACED EXISTING MO	nt for corner and accessories es NUMENT, W/A 5/8" X 18" REBAR W/A STONE CEDAR 4" STOP SIC N43"W N64 44.18' 66.88' (9	A 3-1/4" ALUMN CAP STAMPEN SN POST SURVEY MONUM 1°E S4			
	A-8 REPLACED EXISTING MO SURVEY MONUMENT SIGN WEST 10.96' (TO FACE	NUMENT, W/A 5/8" X 18" REBAR W/A POST DRILL HOLE IN LARGE S N36°E 41.95'	STONE NOTE: NO OTI	D TO ID THE CORNER POSITION. HER WIT'S AVAILABLE AS CORNER ION IS SURROUND BY FARM FIELDS.	· · · · · ·	
	NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE					
Sig	ined by M.P.Asc	//1	Date	7/1/94		
Surveyor's Michigan License No. 16926 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19						
LIBER 8 PAGE 30						