APR 07 1995

For corners in

COMMISSIONAND CORNER RECORDATION CERTIFICATE

Approved By Delta County	
Land Survey Remonumentation	n
Peer Group Under Act 345 Of P.A. Of 1990 On 1949 19, 199	9:

MIC

DAVIS

AND SURVEYOR

NO. 16926

REVISED JAN., 1983

DELTA	Located In:	Corner Code ##						-	
(County)	Located III.	Oolitei Oode -77							=
Public Land Survey	T <u>38 N R 24 W</u> T R T R	C-11 & C-12	Recorded				- Pa	51	<b></b> L
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S T R S T R S T R			nty, idio	. Z	Corre	Reg.	of Dept	s.
	Recorded Plat			8	C D	E F G	Н — 3.—	J K	: L M
	_ , in a field survey onSEPTEME equirements of P.A. 74, Michigan P.A			7-	8-	9-	10	11	12-
current manual of survey ins Management or by a decree of above were in conformance of Court of Law; established,	in conformance with regulations at tructions of the United States Depa of a Court of Law and/or that the corn with the rules of the Michigan Board re-established, monumented, re-	rtment of the Interior, Bureau of er points mentioned in lines 3, 4 of Land Surveyors or by a Decre	in the f Land 7 and 5 8 see of a	19	20-	21	22-	23	24
on this certificat			11 . 12 . 13 .	—30 —31—4	32	33	—27—— —34——	35-	36
<ul> <li>A. Description of origina</li> </ul>	I monument and accessories ar	nd/or subsequent restoration	n:						

C-12 [W1/4 COR S.32] WOOD POST - GEORGE ADAIR, D.S. - 1852 (CEDAR 11"-N78°W-12 LINKS) (CEDAR 6"-S62°E-12 LINKS) NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION

C-11 [NW COR S.32] WOOD POST - GEORGE ADAIR, D.S. - 1852 - (CEDAR 12"-N23"W-39 LINKS) (CEDAR 15'-S13"E-12 LINKS)

M.S.McNABB-1934-FOUND STAKE IN PLACE AT ROAD C/L PI- NO WIT'S NOTED

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-11 [NW COR S.32] NO EVIDENCE OF MCNABB'S 1934 COR FD. SET TEMPORARY COR AT APPROX. C/L PI OF ROADS N & E AND IN LINE WITH FENCE WEST. CHAINED SOUTH 2640' M/L & FD 3/4" IRON PIN AT 1/4 COR, CONT. SOUTH TO TWP LINE & FD IRON STAKE REC'D AT LIBER 4 OF LCR'S ON PG. 30.AS OUR TEMP COR FALLS NEARLY ON A STRAIGHT LINE WITH & PROPORTIONATED DISTANCE NORTH OF THE 1/4 COR & SEC COR FOUND TO THE SOUTH IT WAS DECIDED TO ESTABLISH THIS COR POSITION ON LINE WITH & PROPORTIONATE DISTANCE WORTH OF THE EXISTING MONUMENTS AS FOUND TO THE SOUTH. ACCEPTED THIS POSITION AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.
  - C-12 [W1/4 COR S.32] FOUND IN PLACE A 3/4" X 24" IRON PIN ESTABLISHED BY PERSONS UNKNOWN. CORNER POSITIONS FITS WELL WITH NOT TO WELL DEFINED OCCUPATION E & W. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.

ERED LAND C. Description of monument for corner and accessories established to perpetuate locating the position of the corne C-11 SET 6" BELOW ROAD SURFACE A 5/8" X 18" IRON PIN W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION SURVEY MONUMENT SIGN POST NOTE: CORNER POSITION SURROUNDED BY FARM POWER POLE N57°₩ FIELDS, NO OTHER WIT'S AVAILABLE EAST 30.02' (TO FACE) 18.68' (TO FACE)

C-12 SET OVER EXISTING NON A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION.

POWER POLE CEDAR 7" CEDAR 7" TAMARACK 8" SURVEY MONUMENT SIGN POST \$49°E S36°W WEST N59\*W . N49°E 50.62' 19.00' [TO FACE] 30.47' (TO FACE) 32.02 32.611

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS HOTED OTHERWISE

Signed by Surveyor's Michigan License No. 16926 APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975